



FPL Energy
Seabrook Station

FPL Energy Seabrook Station
P.O. Box 300
Seabrook, NH 03874
(603) 773-7000

JUL 29 2005

Docket No. 50-443

SBK-L-05145

United States Nuclear Regulatory Commission
Attn.: Document Control Desk
Washington, D.C. 20555-0001


Seabrook Station
Inservice Inspection Examination Report

Enclosed is the FPL Energy Seabrook, LLC Inservice Inspection Examination Report for inspections conducted prior to and during the tenth refueling outage that concluded on May 3, 2005. The enclosed report is submitted pursuant to the requirements of paragraph IWA-6240 of the 1995 Edition (including the 1996 addenda) of Section XI of the American Society of Mechanical Engineers (ASME) Boiler and Pressure Vessel Code. Additionally, a copy of this letter and the enclosed report are being submitted to the State of New Hampshire.

Should you have any questions regarding this information, please contact Mr. Michael Ossing, Engineering Support Manager, at (603) 773-7512.

Very truly yours,

FPL Energy Seabrook, LLC


Gene F. St. Pierre
Site Vice President

A047

United States Nuclear Regulatory Commission
SBK-L-05145/Page 2

cc: S. J. Collins, NRC Region I Administrator
V. Nerses, NRC Project Manager, Project Directorate I-2
G.T. Dentel, NRC Senior Resident Inspector

Wayne Brigham, Boiler Inspector
New Hampshire Department of Labor
Inspection Division
PO Box 2076
Concord, NH 03302-2076

Enclosure to SBK-L-05145

FORM OAR-1 OWNER'S ACTIVITY REPORT

Report Number: ISI-SBK-2005

Owner: FPL Energy Seabrook, LLC
P.O. Box 14000
700 Universe Boulevard
Juno Beach, FL 33408-0420

Plant: FPL Energy Seabrook
P.O. Box 300
Seabrook, NH 03874

Unit No. 1 Commercial service date August 19, 1990 Refueling outage no. OR10
 (if applicable)

Current inspection interval 2nd Interval
 (1st, 2nd, 3rd, 4th, other)

Current inspection period 2nd Period
 (1st, 2nd, 3rd)

Edition and Addenda of Section XI applicable to the inspection plan 1995 Edition with 1996 Addenda

Date and revision of inspection plan March 23, 2005 Revision 09

Edition and Addenda of Section XI applicable to repairs and replacements, if different than the inspection plan _____
Same as inspection plan.

CERTIFICATE OF CONFORMANCE

I certify that the statements made in this Owner's Activity Report are correct, and that the examinations, tests, repairs, replacements, evaluations, and corrective measures represented in this report conform to the requirements of Section XI.

Certificate of Authorization No. N/A Expiration Date N/A
 (if applicable)
 Signed Kevin A. Whitney, Sr. Engineer Date June 29, 2005
 Owner or Owner's Designee, Title

CERTIFICATE OF INSERVICE INSPECTION

I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and the State or Province of NEW HAMPSHIRE and employed by HSBCT of Hartford, CT have inspected the items described in this Owner's Activity Report, during the period 1-3-05 to 4-30-05, and state that to the best of my knowledge and belief, the Owner has performed all activities represented by this report in accordance with the requirements of Section XI.

By signing this certificate neither the Inspector nor his employer makes any warranty, expressed or implied, concerning the examinations, tests, repairs, replacements, evaluations, and corrective measures described in this report. Furthermore, neither the Inspector nor his employer shall be liable in any manner for any personal injury or property damage or a loss of any kind arising from or connected with this inspection.

KW Sobel Commissions NH 709
 Inspector's Signature National Board, State, Province, and Endorsements
 Date 7-1-05

TABLE 1
ABSTRACT OF EXAMINATIONS AND TESTS

SBK - 2nd Interval, 2nd Period

Examination Category	Total Examinations Required for The Interval	Total Examinations Credited for This Period	Total Examinations Credited (%) For The Period	Total Examinations Credited (%) To Date for The Interval	Remarks
B-A	24	0	0%	17%	Percentage acceptable per IWB-2412 (a)(2). Relief Request 2IR-1 applied.
B-B	5	1	100%	60%	Relief Request 2IR-2 applied.
B-D	44	10	100%	36%	Percentage acceptable per IWB-2412 (a)(2). Relief Request 2IR-2 applied.
B-F	Included in the Risk-Informed ISI Program.				See Category R-A.
B-G-1	241	54	50%	45%	
B-G-2	74	11	46%	49%	
B-H	Category B-H items are included with Category B-K.				
B-J	Included in the Risk-Informed ISI Program.				See Category R-A.
B-K	1	0	0%	0%	Percentage acceptable per IWB-2412 (a)(5). Relief Request 2IR-12 applied.
B-L-1	There are no B-L-1 pump casing welds.				
B-L-2	1	0	0%	0%	Percentage acceptable per IWB-2412 (a)(4).
B-M-1	There are no B-M-1 valve body welds.				
B-M-2	6	0	0%	50%	Percentage acceptable per IWB-2412 (a)(4). One of each group required when disassembled.
B-N-1	3	0	0%	33%	Percentage acceptable per IWB-2412 (a)(3).
B-N-2	6	0	0%	0%	Percentage acceptable per IWB-2412 (a)(3).
B-N-3	1	0	0%	0%	Percentage acceptable per IWB-2412 (a)(3).
B-O	2	0	0%	50%	Percentage acceptable per IWB-2412 (a)(3).
B-P	7	1	100%	57%	Required each refueling outage.
B-Q	Steam Generator tubing is examined in accordance with Plant Technical Specifications.				
C-A	16	0	0%	25%	

TABLE 1
ABSTRACT OF EXAMINATIONS AND TESTS (continued)

SBK – 2nd Interval, 2nd Period

Examination Category	Total Examinations Required for The Interval	Total Examinations Credited for This Period	Total Examinations Credited (%) For The Period	Total Examinations Credited (%) To Date for The Interval	Remarks
C-B	7	0	0%	29%	
C-C	5	0	0%	40%	
C-D	There are no category C-D items.				
C-F-1	140	22	42%	42%	
C-F-2	157	12	50%	37%	
C-G	There are no category C-G items.				
C-H	25	13	52%	51%	Required each Period.
D-A	11	3	50%	27%	
D-B	17	7	41%	47%	Required each Period. Code Case N-498-4 applied to hydrostatic tests.
E-A	161	152	94%	65%	Required each Period per 10CFR50.55a(b)(ix)(E).
E-C	6	6	100%	50%	Locations identified in Period 1 and require examination in Period 2 and Period 3.
E-D	3	1	100%	67%	
E-G	15	3	100%	73%	Required percentage amended by Code Case N-598.
F-A	202	28	42%	57%	
L-A	24	0	0%	33%	Required every 5 years per IWL-2410(a).
R-A	72	12	50%	50%	Risk-Informed Relief Request approved by NRC TAC No. MB1799.

TABLE 2
ITEMS WITH FLAWS OR RELEVANT CONDITIONS THAT
REQUIRED EVALUATION FOR CONTINUED SERVICE

Examination Category	Item Number	Item Description	Flaw Characterization (IWA-3300)	Flaw or Relevant Condition Found During Scheduled Section XI Examination or Test (Yes or No)
-------------------------	----------------	---------------------	--	--

There were no flaws or relevant conditions that required evaluation for continued service.

**TABLE 3
ABSTRACT OF REPAIRS, REPLACEMENTS, OR CORRECTIVE MEASURES
REQUIRED FOR CONTINUED SERVICE**

SBK – 2nd Interval, 2nd Period

Code Class	Repair, Replacement, or Corrective Measure	Item Description	Description of Work	Flaw or Relevant Condition Found During Scheduled Section XI Examination or Test (Yes/No)	Date Completed	Repair/ Replacement Plan Number
2	<input checked="" type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	MS-PV-3003	Replacement and Machining of Plug Assembly	CHECK IF YES <input type="checkbox"/>	11/10/2003	00W000275
1	<input checked="" type="checkbox"/> Repair <input type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	RC-E-11B	Attachment of Access Platform to Steam Generator Support	CHECK IF YES <input type="checkbox"/>	4/21/2005	01C2836
1	<input checked="" type="checkbox"/> Repair <input type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	RC-E-11C	Attachment of Access Platform to Steam Generator Support	CHECK IF YES <input type="checkbox"/>	4/21/2005	01C2837
1	<input checked="" type="checkbox"/> Repair <input type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	RC-E-11D	Attachment of Access Platform to Steam Generator Support	CHECK IF YES <input type="checkbox"/>	4/20/2005	01C2838
1	<input checked="" type="checkbox"/> Repair <input type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	RC-E-11A	Attachment of Access Platform to Steam Generator Support	CHECK IF YES <input type="checkbox"/>	4/20/2005	01C2990
2	<input checked="" type="checkbox"/> Repair <input type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	2-RC-V-24	Machining of Relief Valve	CHECK IF YES <input type="checkbox"/>	12/29/2003	01RE00116600
2	<input checked="" type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	MS-PV-3001	Replacement and Machining of Plug Assembly	CHECK IF YES <input type="checkbox"/>	11/10/2003	01W000815
3	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	CC-V-256	Bolting Replacement for Pipe to Valve Flange	CHECK IF YES <input type="checkbox"/>	4/21/2005	0219315
3	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	816-SG-11	Addition of Pipe Support	CHECK IF YES <input type="checkbox"/>	12/10/2003	0228266
3	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	816-SG-3	U-Bolt Replacement on Pipe Support	CHECK IF YES <input type="checkbox"/>	12/10/2003	0228266
3	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	CC-TV-130	CS-TV-130 Replacement	CHECK IF YES <input type="checkbox"/>	12/10/2003	0228266
2	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	1-MS-V-394	Trim Replacement	CHECK IF YES <input type="checkbox"/>	12/9/2003	0229034
2	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	RC-E-11A	Machining of Secondary Handhole Cover on S/G "A"	CHECK IF YES <input type="checkbox"/>	10/29/2003	0230433

**TABLE 3
ABSTRACT OF REPAIRS, REPLACEMENTS, OR CORRECTIVE MEASURES
REQUIRED FOR CONTINUED SERVICE**

SBK - 2nd Interval, 2nd Period

Code Class	Repair, Replacement, or Corrective Measure	Item Description	Description of Work	Flaw or Relevant Condition Found During Scheduled Section XI Examination or Test (Yes/No)	Date Completed	Repair/ Replacement Plan Number
2	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	RC-E-11B	Bolting Replacement on Secondary Handhole Cover of Steam Generator	CHECK IF YES <input type="checkbox"/>	10/29/2003	0230439
2	<input checked="" type="checkbox"/> Repair <input type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	RC-E-11B	Machining of Secondary Handhole Cover on S/G "B"	CHECK IF YES <input type="checkbox"/>	10/29/2003	0230439
2	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	RC-E-11D	Replacement of Secondary Manway Cover Bolting	CHECK IF YES <input type="checkbox"/>	10/29/2003	0230452
2	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	RC-E-11D	Replacement of Secondary Manway Cover	CHECK IF YES <input type="checkbox"/>	10/29/2003	0230452
1	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	RC-V-116	Replacement of Code Safety Valve	CHECK IF YES <input type="checkbox"/>	12/10/2003	0230466
1	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	RC-V-117	Replacement of Code Safety Valve	CHECK IF YES <input type="checkbox"/>	12/10/2003	0230466
1	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	RC-V-115	Replacement of Code Safety Valve	CHECK IF YES <input type="checkbox"/>	12/10/2003	0230466
1	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	RC-P-1B	Replacement of Pump Seal Cartridge	CHECK IF YES <input type="checkbox"/>	11/6/2003	0230608
1	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	RC-P-1D	Replacement of Pump Seal Cartridge	CHECK IF YES <input type="checkbox"/>	11/6/2003	0230663
3	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	DG-V-124	Bolting Replacement	CHECK IF YES <input type="checkbox"/>	12/18/2003	0231217
3	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	DG-V-124	Relief Valve Replacement	CHECK IF YES <input type="checkbox"/>	12/18/2003	0231217
2	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	1-CS-FCV-121	Replacement of Valve Internals	CHECK IF YES <input type="checkbox"/>	11/6/2003	0232918
3	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	CC-V-143	Relief Valve Replacement	CHECK IF YES <input type="checkbox"/>	12/4/2003	0233871

TABLE 3
ABSTRACT OF REPAIRS, REPLACEMENTS, OR CORRECTIVE MEASURES
REQUIRED FOR CONTINUED SERVICE

SBK - 2nd Interval, 2nd Period

Code Class	Repair, Replacement, or Corrective Measure	Item Description	Description of Work	Flaw or Relevant Condition Found During Scheduled Section XI Examination or Test (Yes/No)	Date Completed	Repair/Replacement Plan Number
3	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	CC-V-410	Relief Valve Replacement	CHECK IF YES <input type="checkbox"/>	12/17/2003	0233885
3	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	CS-V-148	Relief Valve Replacement	CHECK IF YES <input type="checkbox"/>	12/5/2003	0233893
2	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	CS-V-173	Relief Valve Replacement	CHECK IF YES <input type="checkbox"/>	12/19/2003	0233894
3	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	DM-V-18	Relief Valve Replacement	CHECK IF YES <input type="checkbox"/>	12/11/2003	0233904
3	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	SW-V-32	Replacement of Safety Valve	CHECK IF YES <input type="checkbox"/>	12/5/2003	0233930
3	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	810-RM-3	Replacement of Pipe Snubber	CHECK IF YES <input type="checkbox"/>	11/4/2003	0236422
3	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	DG-V-24A	Replacement of Valve	CHECK IF YES <input type="checkbox"/>	11/10/2003	0240968
3	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	DG-V-23A	Replacement of Valve	CHECK IF YES <input type="checkbox"/>	11/25/2003	0240969
3	<input checked="" type="checkbox"/> Repair <input type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	DG-V-23A	Modification of Valve Disk	CHECK IF YES <input type="checkbox"/>	11/13/2003	0240969
3	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	DG-V-4A	Replacement of Valve	CHECK IF YES <input type="checkbox"/>	11/13/2003	0240972
3	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	DG-V-1A	Replacement of Valve	CHECK IF YES <input type="checkbox"/>	11/13/2003	0240973
3	<input checked="" type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	RMW-1109 & 1109-SG-2	Modification to RMW-1109 and Cutting of Support 1109-SG-2	CHECK IF YES <input type="checkbox"/>	12/29/2003	0300908
3	<input checked="" type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	CS-FCV-111A	Replace and Rotate Valve	CHECK IF YES <input type="checkbox"/>	12/29/2003	0300908

**TABLE 3
ABSTRACT OF REPAIRS, REPLACEMENTS, OR CORRECTIVE MEASURES
REQUIRED FOR CONTINUED SERVICE**

SBK - 2nd Interval, 2nd Period

Code Class	Repair, Replacement, or Corrective Measure	Item Description	Description of Work	Flaw or Relevant Condition Found During Scheduled Section XI Examination or Test (Yes/No)	Date Completed	Repair/ Replacement Plan Number
3	<input checked="" type="checkbox"/> Repair <input type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	CC-V-271	Machining of Valve Nozzle	CHECK IF YES <input type="checkbox"/>	11/26/2003	0302993
3	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	CS-FCV-111A	Replacement of Valve Plug Assembly	CHECK IF YES <input type="checkbox"/>	12/29/2003	0304469
3	<input checked="" type="checkbox"/> Repair <input type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	1109-SG-3	Attachment of CS-FT-111-2 to Pipe Support 1109-SG-3	CHECK IF YES <input type="checkbox"/>	12/29/2003	0304475
2	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	1-CBS-E-16A	Replacement of Bolting on Heat Exchanger	CHECK IF YES <input type="checkbox"/>	11/10/2003	0312432
2	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	RC-E-11A	Replacement of Secondary Manway Cover Bolting	CHECK IF YES <input type="checkbox"/>	10/29/2003	0312825
3	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	SW-1803 & 1805	Bolting Replacement	CHECK IF YES <input type="checkbox"/>	4/28/2005	0319755
3	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	SW-V-28	Replacement of Valve	CHECK IF YES <input type="checkbox"/>	12/3/2004	0324441
2	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	RC-V-24	Replacement of Valve	CHECK IF YES <input type="checkbox"/>	12/29/2003	0324467
3	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	SW-P-41B	Replacement of Pump Assembly	CHECK IF YES <input type="checkbox"/>	12/30/2003	0325166
3	<input checked="" type="checkbox"/> Repair <input type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	SW-P-41(spare)	Rebuilding of Pump Assembly	CHECK IF YES <input type="checkbox"/>	11/9/2004	0341142
3	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	CC-V-264	Relief Valve Replacement	CHECK IF YES <input type="checkbox"/>	4/29/2005	0404751
3	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	CC-V-271	Relief Valve Replacement	CHECK IF YES <input type="checkbox"/>	4/29/2005	0404753
3	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	CC-V-845	Relief Valve Replacement	CHECK IF YES <input type="checkbox"/>	4/18/2005	0404762

**TABLE 3
ABSTRACT OF REPAIRS, REPLACEMENTS, OR CORRECTIVE MEASURES
REQUIRED FOR CONTINUED SERVICE**

SBK - 2nd Interval, 2nd Period

Code Class	Repair, Replacement, or Corrective Measure	Item Description	Description of Work	Flaw or Relevant Condition Found During Scheduled Section XI Examination or Test (Yes/No)	Date Completed	Repair/ Replacement Plan Number
2	<input checked="" type="checkbox"/> Repair <input type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	Manway Cover	Machining of Spare Secondary Manway Cover	CHECK IF YES <input type="checkbox"/>	1/18/2005	0407374
3	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	SW-1802-06 & SKM-05066-2001	Annubar SW-FE-6151 Modification	CHECK IF YES <input type="checkbox"/>	4/20/2005	0415635
2	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	SW-V-30	Valve Replacement	CHECK IF YES <input type="checkbox"/>	3/2/2005	0418202
3	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	SW-1817	Bolting Replacement on Service Water Piping	CHECK IF YES <input type="checkbox"/>	4/20/2005	0441456
3	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	SW-1817-06	Service Water Elbow and 2" Piping Replacement	CHECK IF YES <input type="checkbox"/>	4/20/2005	0441456
3	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	Pipe Flange	Bolting Replacement on Pipe Flange to Valve SW-V-49	CHECK IF YES <input type="checkbox"/>	4/20/2005	0504009
3	<input checked="" type="checkbox"/> Repair <input type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	SW-1810	Attachment of Branch Connection to Service Water Piping	CHECK IF YES <input type="checkbox"/>	4/28/2005	0511095
2	<input checked="" type="checkbox"/> Repair <input checked="" type="checkbox"/> Replacement <input type="checkbox"/> Corrective Measure	MS-PV-3002	Replacement and Machining of Plug Assembly	CHECK IF YES <input type="checkbox"/>	11/24/2003	99W002711