



August 8, 2005
NRC:05:049

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555-0001


Interim Report Concerning an Evaluation of a Deviation Pursuant to 10 CFR 21.21(a)(2)

Enclosed is an interim report concerning an evaluation of a deviation under the provisions of Part 21.

The enclosed report summarizes the actions being taken to assess the potential failure of certain Eaton Electrical Freedom Series Heater Pack models manufactured and supplied between September of 2004 and May of 2005. No customers have observed or reported any adverse operational experience with the Eaton Electrical Freedom Series Heater Pack models. Since the only failures of certain Freedom Series Heater Pack models have occurred during installation or removal of the heater pack only and not during heater operation, there is no reason to believe a substantial safety hazard exists.

Those Framatome ANP customers potentially affected by this matter will be notified and will receive a copy of this interim report.

Sincerely,


Ronnie L. Gardner, Manager
Site Operations and Regulatory Affairs

Enclosure

cc: M.C. Honcharik
Project 728

IEP