



Margie Akbari, MD, FACC
Robert F. Cunnion, MD, FACC

August 18, 2005

U.S. NRC Region I
Atten: Steven Courtemanche
475 Allendale Road
King of Prussia, PA 19406-1415

K-4

*45-23046-01
03020211*

Re: Request for License Renewal
NRC License Number: 45-~~23046~~-01
23046

Dear Steven Courtemanche. *now*

Per our telephone conversation here is the requested documentation you wanted to renew our NRC license.

RIA laboratory work was performed in the past when the P.C. was own and operated under a different physician group at a different location. The group has split up and the previous owners have started a new practice at the original location and have obtained their own license. The Virginia Cardiology, P.C. has not been and will not be performing any RIA laboratory work under Part 31, Section 11 and would like to have this released from the license.

Please contact me at your convenience should you require any additional information.

Sincerely,

Neil C. Smarte, C.N.M.T.
Radiation Safety Officer

NCS

Cc Robert F. Cunnion, M.D. President

137217

NMSS/RGNI MATERIALS-002