NRC FORM 591M PAR (10-2003) 10 CFR 2.201		PECTION REPORT A	u.s. ND COMPLIANCE INSP	NUCLEAR REGULATO	RY COMMISSION
LICENSEE/LOCATION INSPECTED: Defense Intelligence Agency Building 4545 Fowler Road Redstone Arsenal, AL 35898-5500 REPORT Nos 2005-001			2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415		
3. DOCKET NUMBER(S		4. LICENSE NUMBER(S)	5 1	DATE(S) OF INSPECTION	
030-3365	,	01-25316-01		August 02, 2005	314
LICENSEE:					
Nuclear Regulatory Comrof procedures and repres X 1. Based on th 2. Previous vio 3. The violation identified, non-round Nure G-1600,	mission (NRC) rules and rentative records, interview e inspection findings, no valuation(s) closed. (s), specifically described repetitive, and corrective a to exercise discretion, we	regulations and the conditions vs with personnel, and observations were identified. It to you by the inspector as nection was or is being taken, are satisfied.	e as they relate to radiation safets of your license. The inspection ations by the inspector. The instance on-cited violations, are not being and the remaining criteria in the New York wing requirement(s) and Correct	cited because they were	xaminations ollows: e self-
			and/or attached, were in violatio		and are
	Licensee's	Statement of Correct	ive Actions for Item 4,	above.	
corrective actions is made	e in accordance with the reward will be achieved). I unde	equirements of 10 CFR 2.20	will be taken to correct the violat I (corrective steps already taken response to NRC will be require Signatu	, corrective steps which was d, unless specifically req	will be taken,
LICENSEE'S REPRESENTATIVE					
NRC INSPECTOR	Orysia Masnyk Ba	ailey	/RA	1	08-02-2005