NRC FORM 591M PART 1 (10-2003) 10 CFR 2.201 U.S. NUCLEAR REGULATORY COMMISSION SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION			
1. LICENSEE/LOCATION INSPECTED: Tennessee Valley Authority 1101 Market Street Chattanooga, TN 37402-2801		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road	
REPORT Nos   2005-001     3. DOCKET NUMBER(S)   4. LICENSE NUMBER(S)		5. DATE(S) OF INSPECT	
030-32822 LICENSEE:	01-25207-01	August 3, 2005	
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:    Image: I			
Licensee's Statement of Corrective Actions for Item 4, above.   I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested. Title   Printed Name Signature Date   LICENSEE'S REPRESENTATIVE Orysia Masnyk Bailey /RA/ 08-03-2005			