NRC FORM 591M P	ART 1	· · · · · · · · · · · · · · · · · · ·	U	.S. NUCLEAR REGULATO	RY COMMISSION
(10-2003) 10 CFR 2 201			-		
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION					
1. LICENSEE/LOCATION INSPECTED: US Navy			2. NRC/REGIONAL OFFICE		
Pearl Harbor Naval Shipyard			USNRC Region IV		
Pearl Harbor, Hawaii (Permit #53-32253-A1NP)			611 Ryan Plaza Drive, Suite 400 Arlington, Texas 76011-4005		
REPORT NUMBER(S)	2005-002		· · · · · · · · · · · · · · · · · · ·		
3. DOCKET NUMBER(S)		4. LICENSEE NUMBER(S)		5. DATE(S) OF INSPECTION	
030-29462		45-23645-01NA		June 23, 2005	
LICENSEE:		1			
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: Image: I					
4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions) Licensee's Statement of Corrective Actions for Item 4, above.					
corrective actions is ma	de in accordance with the ce will be achieved). I unde	cribed by me to the inspector requirements of 10 CFR 2.20 erstand that no further written ed Name	1 (corrective steps already to response to NRC will be red	aken, corrective steps which	will be taken,
REPRESENTATIVE					
NRC INSPECTOR	James L.	Thompson	/F	RA/	7/13/2005
and the second se					

NRC FORM 591M PART 1 (10-2003)