

## UNITED STATES NUCLEAR REGULATORY COMMISSION REGION IV

## 611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-4005

August 29, 2005

Mr. Jeff Pettigrew Corporate Radiation Safety Officer Precision Energy Services, Inc. 363 North Sam Houston Parkway, Suite 1700 Houston, Texas 77060

SUBJECT: NRC INSPECTION REPORT 030-36570/05-002 (FORM 591M)

Dear Mr. Pettigrew:

This letter and the enclosed NRC Form 591M refer to the inspection conducted on July 18,2005, at your facility in Oklahoma City, Oklahoma. This inspection was an examination of activities conducted under your license as they relate to safety and compliance with the Commission's rules and regulations and with the conditions of your license. Within these areas, the inspection consisted of selected examination of procedures and representative records, and interviews with personnel. The inspection findings were discussed with Mr. Joe Hall of your staff at the conclusion of the inspection. A final telephonic exit was conducted with you on August 25, 2005.

Within the scope of this inspection no violations or deviations were identified; therefore, no response to this letter or the enclosed NRC Form 591M is required.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be made available electronically for public inspection in the NRC Public Document Room or from the NRC's document system (ADAMS), accessible from the NRC Web site at http://www.nrc.gov/reading-rm/adams.html.

Should you have any questions concerning this inspection, please contact Mr. James Thompson at (817) 276-6538 or the undersigned at (817) 860-8287.

Sincerely,

/RA Robert A Brown for/

Mark R. Shaffer, Chief Nuclear Materials Inspection Branch

Docket No.: 030-36570 License No.: 35-26895-02

Enclosure: As stated

Precision Energy Services, Inc.

-2-

cc w/enclosure:

Texas Radiation Control Program Director Oklahoma Radiation Control Program Director

SISP Review Completed: JLT  ADAMS: X_Yes _No Initials: JLT  X_Publicly Available	bcc w/enclosure (via ADAMS distrib): LDWert CLCain MRShaffer JEWhitten JLThompson KEGardin NMIB RIV Materials Docket File (5 <sup>th</sup> floor)						
ADAMS: X_YesNo Initials: JLT  X_Publicly Available	SISP Review Completed: .II T						
X_Publicly Available □ Non-Publicly Available □ Sensitive X Non-Sensitive  DOCUMENT NAME: s:\dnms\!nmib\!thompson\53657002.wpd  RIV:DNMS:NMIB □ C:NMIB  JLThompson □ MRShaffer  /RA/ □ /RA RABrown for/  08/29/05 □ 08/29/05	·						
DOCUMENT NAME: s:\dnms\!nmib\!thompson\53657002.wpd           RIV:DNMS:NMIB         C:NMIB           JLThompson         MRShaffer           /RA/         /RA RABrown for/           08/29/05         08/29/05							
RIV:DNMS:NMIB         C:NMIB           JLThompson         MRShaffer           /RA/         /RA RABrown for/           08/29/05         08/29/05	X Publicly Available □ Non-Publicly Available □ Sensitive X Non-Sensitive						
JLThompson         MRShaffer           /RA/         /RA RABrown for/           08/29/05         08/29/05							
/RA/ /RA RABrown for/ 08/29/05 08/29/05							
08/29/05 08/29/05							
	OFFICIAL RECORD COPY	T=Telephone E=E-mail F=Fax					

NRC FORM 591M PAR	RT 1		U	I.S. NUCLEAR REGULATO	RY COMMISSION			
(10-2003) 10 CFR 2.201								
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION								
1. LICENSEE/LOCATION		2. N	IRC/REGIONAL OFFICE					
Precision Energ	gy Services, Inc.		HONDO D. : IV					
Oklahoma City,	Gue Oklahoma		USNRC Region IV					
Oktanoma Oity,	Okianoma		611 Ryan Plaza Drive, Suite 400 Arlington, Texas 76011-4005					
REPORT NUMBER(S)	05-002		<b>.</b>					
3. DOCKET NUMBER(S)	00 002	4. LICENSEE NUMBER(S)		5. DATE(S) OF INSPECTION				
030-36570		35-26895-02		July 18 - August 2	5 2005			
		00 20000 02		Tay to August 2	0, 2000			
LICENSEE:  The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:								
1. Based on the inspection findings, no violations were identified.								
2. Previous violation(s) closed.								
3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.								
Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):								
4 During this	inspection certain of vo	our activities, as described be	alow and/or attached we	ere in violation of NRC red	uirements and			
		OF VIOLATION, which may						
(Violations and Corrective Actions)								
	Licensee's	Statement of Corrective	e Actions for Item	4, above.				
I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless								
specifically requested. Title		ed Name	Sia	nature	Date			
LICENSEE'S REPRESENTATIVE			0.9		_ 310			
NRC INSPECTOR	James L.	Thompson	//	R <i>A</i> /	8/25/2005			
		-	1					