

September 1, 2005

Larry Arbogast, Radiation Safety Officer
COGEMA Mining, Inc.
935 Pendell Boulevard
P.O. Box 730
Mills, WY 82644

SUBJECT: CHRISTENSEN RANCH POND 4 LEAK - FINAL REPORT, SOURCE
MATERIALS LICENSE SUA-1341 (TAC L60487)

Dear Mr. Arbogast:

On July 8, 2005, COGEMA Mining, Inc. (COGEMA) submitted a letter report regarding the causes of a leak in Pond 4, and the associated corrective actions. As stated during a telephone conversation, on July 25, 2005, the U.S. Nuclear Regulatory Commission (NRC) staff reviewed the report and had no questions, at that time. This letter serves to document our review of the aforementioned Pond 4 report, and that NRC staff has no further questions. If you have any questions, please contact me at 301-415-7182 or by e-mail at sjc7@nrc.gov.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system Agencywide Documents Access and Management System (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/NRC/reading-rm/adams.html>.

Sincerely,

/RA/

Stephen J. Cohen, Project Manager
Uranium Processing Section
Fuel Cycle Facilities Branch
Division of Fuel Cycle Safety
and Safeguards
Office of Nuclear Material Safety
and Safeguards

Docket No.: 40-8502
License No.: SUA-1341

September 1, 2005

Larry Arbogast, Radiation Safety Officer
COGEMA Mining, Inc.
935 Pendell Boulevard
P.O. Box 730
Mills, WY 82644

SUBJECT: CHRISTENSEN RANCH POND 4 LEAK - FINAL REPORT, SOURCE
MATERIALS LICENSE SUA-1341 (TAC L60487)

Dear Mr. Arbogast:

On July 8, 2005, COGEMA Mining, Inc. (COGEMA) submitted a letter report regarding the causes of a leak in Pond 4, and the associated corrective actions. As stated during a telephone conversation, on July 25, 2005, the U.S. Nuclear Regulatory Commission (NRC) staff reviewed the report and had no questions, at that time. This letter serves to document our review of the aforementioned Pond 4 report, and that NRC staff has no further questions. If you have any questions, please contact me at 301-415-7182 or by e-mail at sjc7@nrc.gov.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system Agencywide Documents Access and Management System (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/NRC/reading-rm/adams.html>.

Sincerely,

/RA/

Stephen J. Cohen, Project Manager
Uranium Processing Section
Fuel Cycle Facilities Branch
Division of Fuel Cycle Safety
and Safeguards
Office of Nuclear Material Safety
and Safeguards

Docket No.: 40-8502
License No.: SUA-1341

DISTRIBUTION:

FCFB r/f J. Whitten RIV

ML052430193

OFC	FCFB		FCFB		FCFB			
NAME	SCohen		BGarrett		RNelson			
DATE	08/31/05		09/01/05		09/01/05			

OFFICIAL RECORD COPY