

From: Leanne Harrison *RT*
To: A. Randolph Blough
Date: 4/2/04 8:50AM
Subject: Discussion with Alleger

Randy,
I spoke with the Alleger shortly after our discussion this morning (this is the Alleger who raised concerns regarding the degraded CRD system).

Attached is a more detailed summary. The main points are that he believes the feedwater pipe thinning issue was identified about 18 months ago during the last outage and that Engineering has been addressing the issue since then. Alleger made interesting statement:
"I'm sure the plant would not start up with minimum wall thickness."

Alleger will be paying attention to feedwater pipe vibration issue - this is his biggest concern, but he made no new allegations. He is just concerned that something must be wrong to have pieces of equipment laying on the plant floor from such strong vibrations.

Although he had no other performance issues that he wanted us to follow-up on. He mentioned that based on the return of Chris Bakken - Alleger is now getting the feel that "conservative decisions" are now being made. (I believe his segway for this statement was the decision the plant finally made to buy a special tool needed to fix the CRD leakers).

Let me know if you have any questions.

Thanks,
Leanne

CC: Brian Holian; Daniel Holody; Daniel Orr; David Vito; Eileen Neff; Ernest Wilson;
George Malone; Glenn Meyer; Hubert J. Miller; James Wiggins; Marc Ferdas; Mel Gray; Scott Barber;
Sharon Johnson

241
R

Note to File

RI-2004-A-0027

April 2, 2004 (8:00 am)

Spoke with Alleger to determine if he would provide his home address so that we could provide him correspondence regarding the results of our reviews; to request additional information whether he had any additional concerns (other than the CRD system) or additional details regarding performance issues or any feedwater pipe thinning issues.

Alleger stated that he did not wish to receive any correspondence from us. He noted that he works on the inside and would see any results taken by the licensee.

Alleger clarified that the feedwater pipe thinning issue was identified months ago (he believed approximately 18 months ago during the last refueling outage) and that engineering has been addressing the issue since then. The Alleger stated that he was "sure the plant would not start up with only minimum wall thickness" on this piping.

The Alleger mentioned that the licensee has now committed to buy a new tool for the CRD system (which is a good thing). The Alleger knew that there were 8 leaking CRDs, but that the issue has been addressed by licensee.

Regarding my question of any additional performance issues, the Alleger stated that he is "now getting a feel that the plant is making conservative decisions" and that the return of Chris Bakken is a very good thing. Chris Bakken listens to people at all levels and the Alleger feels that Bakken will be much more effective than Larry Wagner (who was not very effective in that position).

Regarding the impending start-up, the Alleger stated that the biggest issue he can think of is the feedwater pipe vibrations. He stated that he will be watching to see why this occurred. Alleger stated his opinion that he would like to see some sort of instrumentation installed to monitor such vibration to determine the root cause, but had no concerns for us to follow-up on at this time.

Leanne Harrison