NRC FORM 591M PAR (10-2003) 10 CFR 2.201	Т1		U.S. NUCLEAR REG	SULATORY COMMISSION	
	SAFETY INSPECTION	REPORT AND C	OMPLIANCE INSPECTION		
LICENSEE/LOCATION INSPECTED: Southern Consulting, LLC 1208 Highway 47 East Dickson, TN 37055 REPORT Nos 2005-001			2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415		
3. DOCKET NUMBER(S		<u> </u>	5. DATE(S) OF INS	SPECTION	
030-35281	41-2550		August 30, 2		
LICENSEE:					
Nuclear Regulatory Comr of procedures and repres X	mission (NRC) rules and regulations are entative records, interviews with person in the inspection findings, no violations were lation(s) closed. (s), specifically described to you by the epetitive, and corrective action was or into exercise discretion, were satisfied. (ited Violation(s) was/were discussed in the inspection certain of your activities, as one in the satisfied in the inspection certain of your activities, as one is form is a NOTICE OF VIOLATION, were satisfied.	and the conditions of you neel, and observations are identified. The inspector as non-citerists being taken, and the avolving the following reduced by the conditions are identified.	attached, were in violation of NRC require o posting in accordance with 10 CFR 19.	ements and are	
corrective actions is made	30 days, the actions described by me to accordance with the requirements of	to the inspector will be of 10 CFR 2.201 (corre	actions for Item 4, above. taken to correct the violations identified. The course steps already taken, corrective steps are to NRC will be required, unless specifically signature.	s which will be taken,	
LICENSEE'S REPRESENTATIVE					
NRC INSPECTOR	Orysia Masnyk Bailey		/RA/	08-30-2005	