

Docket File Information
**SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION**

| | |
|--|---|
| 1. LICENSEE Lincoln County Memorial Hospital REPORT NUMBER(S) 2005-001 | 2. NRC/REGIONAL OFFICE Region III |
|--|---|

| | | |
|--|--|--|
| 3. DOCKET NUMBER(S) 03014048 | 4. LICENSE NUMBER(S) 24-18689-01 | 5. DATE(S) OF INSPECTION September 1, 2005 |
|--|--|--|

| | |
|---|---|
| 6. INSPECTION PROCEDURES USED 87131 | 7. INSPECTION FOCUS AREAS 03.01 - 03.07 |
|---|---|

SUPPLEMENTAL INSPECTION INFORMATION

| | | | |
|------------------------------------|-------------------------|--|--|
| 1. PROGRAM CODE(S) 02121 | 2. PRIORITY 5 | 3. LICENSEE CONTACT Leslie Lindsay, CNMT | 4. TELEPHONE NUMBER 636-528-8551 |
|------------------------------------|-------------------------|--|--|

Main Office Inspection Next Inspection Date: September 2010

Field _____

Temporary Job Site _____

PROGRAM SCOPE

The licensee was a medical facility located in Troy, Missouri, with authorization by the license to use any byproduct material identified in 10 CFR 35.100 and 35.200. One nuclear medicine technologist routinely performs 1-5 procedures/administrations per day with the majority being cardiac tests or bone scans. Licensed material is received as unit doses from a local St. Louis, Missouri, nuclear pharmacy. No diagnostic I-131 administered. No change in RSO or management since the previous inspection.

Performance Observations

During the inspection, the licensee's nuclear medicine technologist demonstrated/discussed: (1) survey meter use and calibration; (2) package receiving and check-in procedures; (3) unit dose prep and safe use; (4) package wipe test counting; (5) dosimetry; (6) dose calibrator tests; (7) waste handling; (8) security of licensed material; (9) RAM transportation; and (10) quarterly radiation safety program audits.