



**Docket File Information****SAFETY INSPECTION REPORT  
AND COMPLIANCE INSPECTION**

1. LICENSEE <b>Livonia Internal Med Assoc</b> REPORT NUMBER(S) <b>2005-001</b>		2. NRC/REGIONAL OFFICE <b>Region III</b> <b>2443 Warrenville Road</b> <b>Lisle, IL 60532</b>	
3. DOCKET NUMBER(S) <b>030-34560</b>		4. LICENSE NUMBER(S) <b>21-32033-01</b>	5. DATE(S) OF INSPECTION <b>9/15/05</b>
6. INSPECTION PROCEDURES USED <b>87130</b>		7. INSPECTION FOCUS AREAS <b>03.01-03.07</b>	

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM CODE(S) <b>2220</b>	2. PRIORITY <b>3</b>	3. LICENSEE CONTACT <b>Ray Carlson</b>	4. TELEPHONE NUMBER <b>734/455-4230</b>
-----------------------------------	-------------------------	---	--

Main Office Inspection      Next Inspection Date: 9/2008

Field Office \_\_\_\_\_

Temporary Job Site \_\_\_\_\_

**PROGRAM SCOPE**

Licensee is a small cardiology practice located in Livonia, Michigan. This licensee uses only unit doses of technetium-99m for cardiac studies supplied by Cardinal Health. The licensee has one technician performing patient studies. The licensee sees approximately 5 patients per day at the clinic.

**Performance Observations**

The inspector toured the facility and conducted interviews of the staff. Each appeared knowledgeable in radiation safety and isotope handling techniques. Package receipt procedures were demonstrated for the inspector as well as rad waste handling practices. Independent surveys by the inspector did not detect any abnormal reading and were within the expected range.

The inspector observed the nuclear medicine staff perform injections of radiopharmaceuticals. Techniques employed by the staff demonstrated good handling practices as well as adequate knowledge of radiation safety. During the course of the inspection, no abnormalities were noted.