NRC FORM 591M PART	Г 1		ι	J.S. NUCLEAR REGULATO	RY COMMISSION
(10-2003) 10 CFR 2.201					
•	SAFETY INSPEC	TION REPORT A	ND COMPLIANCE	EINSPECTION	
1. LICENSEE/LOCATION INSPECTED:			2. NRC/REGIONAL OFFICE		
US Navy Southwest Regional Maintenance Center			USNRC Region IV		
San Diego, California (Permit # 04-55236-A1NP)			611 Ryan Plaza Drive, Suite 400 Arlington, Texas 76011-4005		
(Permit # 04-552	236-A1NP)		Arlington, Texas	76011-4005	
REPORT NUMBER(S)	2005-004				
3. DOCKET NUMBER(S) 030-29462		4. LICENSEE NUMBER(S) 45-23645-01NA		5. DATE(S) OF INSPECTION August 3, 2005	
LICENSEE:		45-25045-0 TNA		August 3, 2003	
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X					
cited. This form			v and/or attached, were in vio to posting in accordance wit	lation of NRC requirements a h 10 CFR 19.11.	nd are being
	Licensee's	Statement of Correct	tive Actions for Item 4	, above.	
corrective actions is made when full compliance will be	in accordance with the record achieved). I understand	quirements of 10 CFR 2.201 that no further written respon	(corrective steps already takense to NRC will be required, u	. , ,	be taken, date
Title LICENSEE'S	Print	ed Name	Siç	gnature	Date
REPRESENTATIVE					
NRC INSPECTOR James L. Thompson			RA/	8/3/2005	