NRC FORM 591M PART 1 (10-2003)			J.S. NUCLEAR REGULATO	DRY COMMISSION			
10 CFA 2.201							
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION							
1. LICENSEELOCATION INSPECTED: Dearborn County	Nogorta	2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region III					
Dearborn County Hospital		2443 Warrenville Road Suite 210					
REPORT 2008-001		Lisle, Illinois 60532-4351					
3. DOCKET NUMBER(S)	4. LICENSEE NU	MBER(S)	5. DATE(S) OFT	NSPECTION			
030-12564	13-1732	7-01	01 Oct. 18, 2005				
LICENSEE:			inerge on they relat				
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection							
1. Based on the inspection findings, no violations were identified.							
2. Previous violation(s) closed.							
3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.							
Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s);							
4. During this inspection certain of ye	our activities, as described being	w and/or attached were in v	iolation of NBC requirement	and are being			
cited. This form is a NOTICE OF VIC	LATION, which may be subject	t to posting in accordance wi	th 10 CFR 19.11.	and are being			
(Violations and Corrective Actions)							
Licensee's Statement of Corrective Actions for Item 4, above. I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of							
corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.							
Title Pr	inted Name	Sig	nature	Date			
LICENSEE'S REPRESENTA							
NRC INCRECTOR Deborah A. P	iskura	Sthefure)	u. l.a.l.			
INSPECTOR DEBOTATIA.P		1 NONBAUR		10/18/05			

.

NRC FORM 591M	PART 3			I.S. NUCLEAR REGULATORY			
(10-2003) 10 CFR 2.201		Docket File	Information	COMMISSION			
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION							
1. LICENSEE			2. NRC/REGIONAL OFFICE Region III				
Dearborn County Hospital REPORT NUMBER(S) 2005-001		2443 Warrenville Road, Suite 210 Lisle, IL 60532		Road, Suite 210			
3. DOCKET NUMBER(S) 030-12564		4. LICENSE NUMBER(S) 13-17327-01	·	5. DATE(S) OF INSPECTION October 18, 2005			
87130, 87131 and 87132		7. INSPECTION FOCUS AREAS 03.01, 03.02, 03.03, 03.04, 03.05, 03.06, 03.07, and 03.08					
SUPPLEMENTAL INSPECTION INFORMATION							
1. PROGRAM CODE(S) 2. 02120	PRIORITY G 3	3. LICENSEE CONTACT Bruce Canfield,	CNMT, RSO	4. TELEPHONE NUMBER 812.537.1010			
X Main Office	Inspection		Next Inspection Date:	Oct. 2008			
Field							
Temporary .	Job Site						
	· · · · · · · · · · · · · · · · · · ·	PROGRA	MSCOPE				
This licensee was a 100-bed community hospital and authorized to use licensed material permitted by Sections 35.100, 35.200, 35.300, and I-125 and Pd-103 for permanent implants. The nuclear medicine department was staffed with three full-time and two part-time technologists who performed approximately 200 diagnostic nuclear medicine procedures per month. The licensee received unit doses from a licensed radiopharmacy and performed a full spectrum of nuclear diagnostic imaging studies. Typically, in a year, the hospital treated 1-2 cases of hyperthyroidism using 8-30 mCi of I-131. Radioiodine is obtained from the pharmacy in capsule form. The radiation therapy activities are performed by contract medical physicists and dosimetrists. Brachytherapy activities were limited to I-125 or Pd-103 permanent implants. The licensee performed 3-5 I-125 or Pd-103 permanent prostate implants (ultrasound guided) per year. This inspection consisted of interviews with licensee personnel, a review of select records, tour of the nuclear medicine department, and independent measurements.							
NRC FORM 591M PART 3 (1)							