

Tier / Group	Randomly Selected K/A	Reason for Rejection
RO 1/1	022 2.4.50	#6 Cannot write an Emergency Plan K/A against this EAPE. Replaced with examiner concurrence with 027 2.1.20.
RO 1/1	056 AA2.42	#11 Unable to write an acceptable question on this K/A. Randomly replaced with 056 AA2.17.
RO 1/1	E04 EA2.1	#15 SRO-only K/A as involves selection of procedures, not appropriate for RO exam. Randomly replaced with E04 EA1.1.
RO 1/2	003 AK3.07	#20 PI procedurally is not allowed to operate with a dropped rod, so unable to write a TS question on this operation. Randomly replaced with 067 AK3.04 as no K3 level K/A's could be used for this APE.
RO 1/2	068 AA2.01	#22 PI CR evacuation places SRO's in locations where SG level is determined and acted upon. Randomly replaced with 068 AA2.07.
RO 2/1	007 K5.02	#33 Unable to write question on this K/A due to plant method of drawing a pressurizer bubble. K/A previously rejected on 2004 exam. Randomly replaced with 013 K5.02 as no other 007 K5's are above 2.5.
RO 2/1	026 A3.02	#40 Equipment not installed at PI, replaced with 039 A3.02 (randomly selected system as no other A3 K/A available for system 026)
RO 2/1	073 K3.01	#50 Radiation effluent releases for PRM already part of NRC JPM exam and similar to other questions (i.e. 068 K6.10) on NRC and audit. No other 073 K3 K/A's exist. First randomly replaced 073 K3.01 with 078 K3.03. This resulted in no 073 system selected, so replaced duplicate selected system K/A 063 A4.03 with 073 A4.03.
RO 2/1	063 A4.03	Replaced with 073 A4.03 per above.
RO 2/1	078 2.2.25	#53 Instrument air not TS related equipment at PI, replaced with 059 2.2.12 (randomly selected system as no other G 2.2 K/A's available for system 078).
RO 2/1	103 A2.05	#55 Emergency Containment Entry JPM is part of audit exam, unable to write question that is not repetitive. Replaced with 007 A3.01 as 103 A2.04 is already selected and system 007 was only 2/1 system not already selected. A3.01 selected with A3 category chosen as only A3 K/A and Tier 2 only had 2 A3's previously selected.

SRO 1/1	027 AA2.10	#77 Two 027 EAPE K/As randomly selected initially, this one replaced as similar to audit scenario malfunction. Randomly replaced with 038 EA2.02.
SRO 1/1	057 AA2.18	#81 Cannot write SRO level question on this K/A. Randomly replaced with 005 AA2.01.
SRO 1/2	024 AA2.04	#82 Cannot write SRO level question on this K/A. Randomly replaced with 069 AA2.01.
SRO 1/2	060 AA2.03	#84 Cannot write SRO level question on this K/A. Randomly replaced with 037 2.1.2.
SRO 2/1	004 A2.19	#86 Unable to write an acceptable SRO level question on this K/A. Randomly replaced with 004 A2.06.
SRO 2/2	011 A2.04	#91 WD program did not include Fuel Handling System 34 K/A's as required by Rev 9. Per discussion with Chief Examiner on 1/19/05, randomly replaced one Tier 2/Gp 2 SRO System with randomly selected fuel handling system K/A 034 A2.02. A satisfactory question could not be written on this K/A due to limited exposure/training of plant SRO's on cask handling. Substituted 034 A2.03 as A2.01 only other choice and it was too similar to #8.
SRO G	2.4.34	#100 Cannot write SRO level question on an RO task K/A. Randomly replaced with 2.4.1.