

## UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION I 475 ALLENDALE ROAD KING OF PRUSSIA, PENNSYLVANIA 19406-1415

October 31, 2005

Docket No. 03013667 License No. 45-15154-03

Will Iseman
Vice President of Operations
Danville Regional Medical Center
142 South Main Street
Danville, VA 24541

SUBJECT: INSPECTION NO. 03013667/2005001

Dear Mr. Iseman:

On July 12, 2005, Willie Lee of this office conducted a safety inspection at the above address of activities authorized by the above listed NRC license. The inspection was an examination of your licensed activities as they relate to radiation safety and to compliance with the Commission's regulations and the license conditions. The inspection consisted of observations by the inspector, interviews with personnel, and a selected examination of representative records. The enclosed inspection report documents the findings of the inspection, which were discussed separately with you, Peter Leider, M.D. and George Sherouse, Ph.D. of your staff by telephone at the conclusion of the inspection on September 28, 2005. The report identifies that on July 12, 2005, you did not secure or maintain constant surveillance over a High Dose Rate Remote Afterloader containing licensed material.

You will be advised by separate correspondence of the results of our enforcement deliberations.

Current NRC regulations are included on the NRC's website at <a href="www.nrc.gov">www.nrc.gov</a>; select Nuclear Materials; Medical, Industrial, and Academic Uses of Nuclear Material; then Toolkit Index page. The current Enforcement Policy is included on the NRC's website at <a href="www.nrc.gov">www.nrc.gov</a>; select What We Do, Enforcement, then Enforcement Policy. Or you may obtain these documents by contacting the Government Printing Office (GPO) toll-free at 1-888-293-6498. The GPO is open from 7:00 a.m. to 9:00 p.m. EST, Monday through Friday (except Federal holidays).

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be made available electronically for public inspection in the NRC Public Document Room or from the NRC's document system (ADAMS), accessible from the NRC Web site at <a href="http://www.nrc.gov/reading-rm/adams.html">http://www.nrc.gov/reading-rm/adams.html</a>. The enclosed inspection report will not be made available for public inspection in the Public Document Room or electronically from ADAMS because it contains specific information concerning the isotopes, activities and locations of radioactive material authorized by your license.

W. Iseman 2 Danville Regional Medical Center

Your cooperation with us is appreciated.

Sincerely,

Original signed by George Pangburn

George Pangburn, Director Division of Nuclear Materials Safety

Enclosure:

Inspection Report No. 03013667/2005001 (Not Public in ADAMS)

CC:

Peter J. Leider, M.D., Radiation Safety Officer Commonwealth of Virginia

W. Iseman 3 Danville Regional Medical Center

Distribution:

D. J. Holody, RI

S. Villar, RI

DOCUMENT NAME: E:\Filenet\ML053070059.wpd

SISP Review Complete: <u>WLee</u>
After declaring this document "An Official Agency Record" it <u>will</u> be released to the Public.

To receive a copy of this document, indicate in the box: "C" = Copy w/o attach/encl "E" = Copy w/ attach/encl "N" = No copy

OFFICE	DNMS/RI	Ν	DNMS/RI	DNMS/RI		
NAME	Wlee/WJL		Phenderson/PDH	GPangburn/GCP		
DATE	10/27/05		10/29/05	11/02/05		