NRC FORM 591M PART 1 (10-2003) 10 CFR 2.201 SAFETY INS	SPECTION REPORT AN	U.S. NUCLEAR REGUL  D COMPLIANCE INSPECTION	ATORY COMMISSION
LICENSEE/LOCATION INSPECTED:     Lockheed Martin Commercial Space Systems     100 Campus Drive     Newtown, Pennsylvania 18940  REPORT Nos 2005-001		2. NRC/REGIONAL OFFICE  U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415	
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE(S) OF INSPE	CTION
03012894	37-02006-09	October 20, 20	
LICENSEE:		2 333.23. 23, 23	
The inspection was an examination of the activities Nuclear Regulatory Commission (NRC) rules and of procedures and representative records, intervie  X	regulations and the conditions aws with personnel, and observativiolations were identified.  Red to you by the inspector as nor action was or is being taken, an ere satisfied.  Red discussed involving the following the followi	of your license. The inspection consisted of selec-	tive examinations as follows:  were self- Policy,
I hereby state that, within 30 days, the actions des corrective actions is made in accordance with the date when full compliance will be achieved). I und	scribed by me to the inspector w requirements of 10 CFR 2.201	(corrective steps already taken, corrective steps w	hich will be taken,
REPRESENTATIVE  NRC INSPECTOR Stephen Hamma	nn	/RA/	10/20/2005