NRC FORM 591M PAR (10-2003) 10 CFR 2.201				U.S. NUCLEAR REGULATO	RY COMMISSION
			AND COMPLIANCE II		
 LICENSEE/LOCATION INSPECTED: PHC-Martinsville, Inc. Dba Memorial Hospital of Martinsville and Henry Cty. Martinsville, VA 24115-4788 			2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415		
REPORT Nos 2005		4 LICENCE NUMBER/O			
 DOCKET NUMBER(\$ 03003365 	>)	4. LICENSE NUMBER(S) 45-13692-01		5. DATE(S) OF INSPECTION 8/23 & 9/20/2005	JN
LICENSEE:		10 10002 01		0/20 Q 0/20/2000	
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X					
			w and/or attached, were in visubject to posting in accorda	olation of NRC requirements a ince with 10 CFR 19.11.	and are
corrective actions is made	30 days, the actions desc e in accordance with the r e will be achieved). I unde	cribed by me to the inspector requirements of 10 CFR 2.2 rrstand that no further written thed Name	01 (corrective steps already to response to NRC will be re	violations identified. This state taken, corrective steps which of quired, unless specifically req gnature	will be taken,