NRC FORM 591M PART 1				U.S. NUCLEAR REGULATO	DRY COMMISSION
(10-2003) 10 CFR 2.201					
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION					
1. LICENSEE/LOCATION INSPECTED: Fairfax Heart Associates, PC 3299 Woodburn Road Annandale, Virginia 22003			Region I, 475 Alle	ulatory Commission ndale Road	
REPORT Nos 2005-001			King of Prussia, F	ennsylvania 19406-1	415
3. DOCKET NUMBER(S)	4. LICEN	SE NUMBER(S)	5. DATE(S) OF INSPECT	ION
030-36772	45-30	978-01		October 272005	
LICENSEE:					
The inspection was an examination of the activiti Nuclear Regulatory Commission (NRC) rules and of procedures and representative records, intervi 1. Based on the inspection findings, no 2. Previous violation(s) closed.	d regulation iews with p	ns and the con- ersonnel, and o	ditions of your license. The observations by the inspector	inspection consisted of sele	ctive examinations
3. The violation(s), specifically describ identified, non-repetitive, and corrective NUREG-1600, to exercise discretion, w	e action wa	s or is being ta			
Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):					
4. During this inspection certain of you being cited. This form is a NOTICE OF					nents and are
Licensee's Statement of Corrective Actions for Item 4, above.					
I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.					
LICENSEE'S REPRESENTATIVE CORE T	- RA	INGR	hull F. P	ignature	Date 10)27 75
NRC INSPECTOR John Nicholson			John Mis	halm	10/27/05
NRC FORM 591M PART 1 (10-2003)		P	Vinspection records 2005V	R45-30978-01.05-001.591P1	.FairfaxHeart.wpd