

Dominion Nuclear Connecticut, Inc.  
5000 Dominion Boulevard, Glen Allen, Virginia 23060  
Web Address: www.dom.com



December 15, 2005

U. S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
One White Flint North  
11555 Rockville Pike  
Rockville, MD 20852-2738

Serial No.: 05-100A  
MPS Lic/RWM Rev 0  
Docket No.: 50-423  
License No.: NPF-49

**DOMINION NUCLEAR CONNECTICUT, INC.**  
**MILLSTONE POWER STATION UNIT 3**  
**WITHDRAWAL OF 10 CFR 50.55a REQUEST IR-2-37,**  
**TEMPORARY NON-CODE REPAIR OF A BRAZED JOINT**  
**IN SERVICE WATER SYSTEM DRAIN LINE**

In a letter dated May 9, 2005, Dominion Nuclear Connecticut, Inc. (DNC) requested relief from the Section XI requirements of the American Society of Mechanical Engineers (ASME) Boiler and Pressure Vessel Code for Millstone Power Station Unit 3 (MPS3), pursuant to 10 CFR 50.55a(g)(5)(iii). This request was based on the impracticality of performing ASME Code repairs to a brazed joint on a 3-inch drain line from the 'A' train service water header during plant operation.

During the recent refueling outage for MPS3 completed on October 27, 2005, DNC completed repairs to the 3-inch drain line of the 'A' train service water header. Therefore, DNC is withdrawing its relief request IR-2-37.

If you should have any questions regarding this submittal, please contact Mr. Paul R. Willoughby at (804) 273-3572.

Very truly yours,

A handwritten signature in black ink, appearing to read "L. Hartz", is written over a horizontal line.

Leslie N. Hartz  
Vice President - Nuclear Engineering

Attachments: None

Commitments contained within this letter: None

cc: U. S. Nuclear Regulatory Commission  
Region I  
475 Allendale Road  
King of Prussia, PA 19406-1415

Mr. V. Nerses  
Project Manager, Millstone Units 2&3  
U. S. Nuclear Regulatory Commission  
One White Flint North  
11555 Rockville Pike  
Mail Stop 8 C2  
Rockville, MD 20852-2738

Mr. S. M. Schneider  
NRC Senior Resident Inspector  
Millstone Power Station