



OCT 18 2004

L-2004-236
10 CFR 50.36

William D. Travers
Regional Administrator
U. S. Nuclear Regulatory Commission
Atlanta Federal Center
61 Forsyth Street, S. W., Suite 23T85
Atlanta, GA 30303

Re: Turkey Point Unit 3
Docket No. 50-250
Steam Generator Tube Plugging 15-Day Special Report

In accordance with Turkey Point Technical Specification 4.4.5.5.a, the subject Special Report is submitted pursuant to Technical Specification 6.9.2 for Turkey Point Unit 3, as a result of the End of Cycle 20 inservice inspection of steam generator tubes.

The Turkey Point Unit 3 steam generators were inspected from October 6, 2004, through October 14, 2004. No tubes required plugging in steam generators 3A, 3B or 3C as a result of these examinations.

Should there be any questions, please contact Walter Parker at 305-246-6632.

Very truly yours,

A handwritten signature in black ink that reads "Terry O. Jones". The signature is written in a cursive style with a large, prominent initial "T".

Terry O. Jones
Vice President
Turkey Point Nuclear Plant

OIH

cc: USNRC, Document Control Desk, Washington, D.C.
Senior Resident Inspector, USNRC, Turkey Point Plant