

U.S. NUCLEAR REGULATORY COMMISSION		Date: 1/5/2006
TELEPHONE CONVERSATION RECORD		Time: 16:30
Mail Control or Report No(s).	138149	License No(s). 29-31118-01 Docket No(s). 030-37111
Name of Licensee:	Peter Lenchur, M.D.	
Name of Participant(s):	Michael Lairmore, Medical Consultant for licensee Steven Courtemanche, Health Physicist NRC	
Telephone No.	201-693-2277 610-337-5075	
Subject: <small>(NOTE: This will be used as the Documents Title in ADAMS)</small>	Deficiency telephone call.	
Summary:	I spoke with Mr. Lairmore concerning his client's application for a license and the additional information that was needed. (1) I needed a statement from the licensee that the place of use indicated on the license was not occupied by any other NRC licensee. (2) The diagram of the facility needs to indicate what is on the other sides of the walls of the imaging room and the hot lab. (3) In future applications, Mr. Lairmore should not used the outdated reference to NUREG-1556, Vol. 9, dated October 2002, but the NUREG-1556, Vol. 9, Rev. 1, dated May 2005. I provided Mr. Lairmore with the Mail Control Number for the licensing action and he stated that he would process the reply as quickly as possible.	
Action Required:	Place in ADAMS	
Document Availability:	<input type="checkbox"/> Publicly Available <input checked="" type="checkbox"/> Non-Publicly Available <input checked="" type="checkbox"/> Non-Sensitive <input type="checkbox"/> Non-Sensitive Copyright <input type="checkbox"/> Sensitive <input type="checkbox"/> Sensitive Copyright <input type="checkbox"/> Immediate Release <input type="checkbox"/> Normal Release <input type="checkbox"/> Delay Release Date	
Prepared & SISP Review Completed By:	/ RA / Steven Courtemanche Date: 1/5/2006	