

January 4, 2006

TO:
Document Control Desk
US Nuclear Regulatory Commission
Washington DC 20555

CC:
Mr. Mark Shaffer
Chief, Nuclear Materials Inspection Branch
Nuclear Regulatory Commission Region IV
611 Ryan Plaza Drive Ste 400
Arlington, TX 76011-4005

Subject: NRC Inspection Report 99-90004/05-002 and Notice of Violation Reply

In response to our Violation, We were unaware of any wrongdoing on our part. We were only made aware to our infraction in March of 2005 when the Nuclear Regulatory commission paid us a visit to inspect our facility.

Immediately after notification, we removed all Lamps containing the KR-85 substance and purchased new lamps from Phillips USA to replace the ones that were in violation. All of our lamps that were in violation were either sent back to Phillips or were destroyed.

In order to prevent any future violations, we are no longer accepting any fixtures containing lamps with KR-85 from our supply company in Italy. All fixtures coming in are sent without lamps. We are purchasing all new lamps from Phillips USA.

At this time, we are fully compliant with all known regulations. If there are any additional questions, please feel free to contact me.

Thank you,
Michael Graham
Customer and Technical Service Manager
Coemar USA
10360 NW 53rd. St
Sunrise FL, 33351
(954)578-8881

JE09