

FIELD REPORT

RECEIVED

Terracon
Consulting Engineers & Scientists

Project: Charles Blvd RR Bridge	
Location: Greenville, NC	
Date: 10-26-05	Job No.: 70053095
Contractor:	Owner: City of Greenville
Present at Site: Eugene Seagroves, III	

1:00


Terracon Consultants, Inc.
5240 Green's Dairy Road
Raleigh, North Carolina 27616
Phone 919.873.2211
Fax 919.873.9555
www.terracon.com

THE FOLLOWING WAS NOTED:

As requested a representative of Terracon met with Mr. Carson Fisher with the City of Greenville. Coating specifications were reviewed for the coating system for the referenced project.

The coating system calls for a prime, intermediate, and final coat. It is understood that Terracon personnel will visit the site to inspect the surface preparation prior to application of the first coat followed by the visual and spot inspection of the dry film thickness of each subsequent coat.

Terracon personnel will not be present during the surface preparation mixing or application of the several coats and therefore no warranty is implied as to the proper material, mixing, ambient conditions, or application of the coating system.



Scott Anderson
Raleigh NDE Manager