



NRC ITS TRACKING

NRC Reviewer

<u>ID</u>	200510281133	Conference Call Requested? No
<u>Category</u>	Discussion	
<u>ITS Information</u>	<u>ITS Section:</u> 5.0 <u>ITS Number:</u> BSI 8	<u>DOC Number:</u> L.5 <u>JFD Number:</u> None <u>Bases JFD Number:</u> None
<u>Comment</u>	<p>This is a Beyond Scope Issue (TAC No. MC7611) CTS 6.8.B.2 specifies that the integrated leak test requirements for each system outside containment that could contain highly radioactive fluids during a serious transient or accident must be performed at a refueling cycle interval or less. CTS 6.8.B also states that CTS 4.0.B is applicable (25% grace period is allowed). ITS 5.5.2.b specifies that the same test must be performed at least once per 24 months and also states that the provisions of ITS SR 3.0.2 are applicable. You request increasing the CTS surveillance frequency from 18 months to 24 months, with a maximum of 30 months accounting for the allowable grace period. There were no questions or comments by NRC staff regarding this issue.</p>	
<u>Issue Date</u>	10/28/2005	
<u>Close Date</u>	Resolution requires change to: None Docket Response Required? No	

▶ Responses

Date Created: 10/28/2005 11:33 AM by Terry Beltz
 Last Modified: 11/29/2005 01:37 PM

Close	View By NRC Owner	View By Item Number
-------	-------------------	---------------------

LICENSEE COMMENTS

<u>ID</u>	200510281133	<u>Validation Required?</u> No
<u>Response Submitted</u>	11/03/2005	
<u>Comment</u>	Monticello acknowledges that there are no questions or comments concerning this Beyond Scope Issue.	

Date Created: 11/03/2005 03:20 PM by Jerry Jones
 Last Modified: 11/03/2005 03:20 PM