

From: Richard McKinley
To: McComasVan@aol.com
Date: 1/18/06 9:35AM
Subject: Survey of Virginia Urology at Mechanicsville(Hanover)

License No.:45-25582-01
Docket No:03035941
Control No: 138114

Dear Mr. McComas:

With regard to the survey that you performed at the above location on November 2, 2005, I have the following questions:

1) You apparently surveyed for lost seeds with an ion chamber. Does this instrument have the necessary sensitivity to find a seed that might not be in an exposed location? I would prefer to see the results of a survey conducted with a Nal probe.

2) Seeds were stored in the storage room at one time. Did you check to see if any had been left in storage after the last implant?

Please note that you may not reply to this letter by return e-mail. Your reply must be in writing by letter or facsimile (610-337-5269). If we do not receive a reply from you within 30 calendar days from the date of this e-mail, we will assume that you do not wish to pursue your application.
Thank you for your cooperation.

Sincerely,
Richard McKinley
Health Physicist
U.S. NRC

CC: Rwm1

Mail Envelope Properties (43CE5331.342 : 16 : 27049)

Subject: Virginia Urology, 45-25582-01, 03035941, Control No. 138114
Creation Date: Wed, Jan 18, 2006 9:39 AM
From: Richard McKinley

Created By: RWM1@nrc.gov

Recipients

nrc.gov
kp1_po.KP_DO
LAT (LAT)

Post Office
kp1_po.KP_DO

Route
nrc.gov

Files	Size	Date & Time
MESSAGE	1570	Wednesday, January 18, 2006 9:39 AM
Survey of Virginia Urology at Mechanicsville(Hanover).mlm		1920 Wednesday,
January 18, 2006 9:36 AM		

Options

Expiration Date: None
Priority: Standard
Reply Requested: No
Return Notification: None

Concealed Subject: No
Security: Standard