NRC FORM 591M PAR (10-2003) 10 CFR 2.201	Т 1		U.S	S. NUCLEAR REGULATO	RY COMMISSION
10 CFR 2.201	SAFETY INSP	PECTION REPORT ANI	O COMPLIANCE INS	SPECTION	
LICENSEE/LOCATION INSPECTED:     Montclair Cardiology Group, PA     123 Highland Avenue, Suite 302     Glen Ridge, New Jersey 07028  REPORT Nos 03036897/2006-001			2. NRC/REGIONAL OFFICE  U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415		
3. DOCKET NUMBER(S		4. LICENSE NUMBER(S)	5	. DATE(S) OF INSPECTION	ON
030-36897		29-31027-01		01/17-18/2006	
The inspection was an ex Nuclear Regulatory Comr of procedures and repres  X 1. Based on th  2. Previous vio  3. The violation identified, non-r NUREG-1600,	mission (NRC) rules and rentative records, interview is inspection findings, no validation(s) closed.  (s), specifically described repetitive, and corrective a to exercise discretion, well	conducted under your license a egulations and the conditions of swith personnel, and observational violations were identified.  I to you by the inspector as nonction was or is being taken, and	f your license. The inspect ons by the inspector. The inspector in the inspector.	ifety and to compliance with ion consisted of selective e inspection findings are as formal formal for the second formal	xaminations ollows: e self-
being cited. Thi	Licensee's 30 days, the actions desc	activities, as described below ar //OLATION, which may be subj	ect to posting in accordance  Te Actions for Item 4  I be taken to correct the vio	e with 10 CFR 19.11.  I, above.  lations identified. This state	ement of
	e will be achieved). I under	equirements of 10 CFR 2.201 ( rstand that no further written res ted Name	sponse to NRC will be requi		
REPRESENTATIVE  NRC INSPECTOR	Steven R. Courter	manche	/R	<b>'A</b> /	01/18/06