

#### UNITED STATES NUCLEAR REGULATORY COMMISSION REGION IV 611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-4005

February 15, 2006

Jeffrey S. Forbes Vice President Operations Arkansas Nuclear One Entergy Operations, Inc. 1448 S.R. 333 Russellville, AR 72801-0967

## SUBJECT: ARKANSAS NUCLEAR ONE, UNIT 1 - NRC RETAKE EXAMINATION REPORT 05000313/2006301

Dear Mr. Forbes:

On January 12, 2006, the U.S. Nuclear Regulatory Commission (NRC) completed an examination at your Arkansas Nuclear One, Unit 1. The enclosed examination report documents the examination results, which were discussed on January 12, 2006, with Mr. Randall Martin of your staff.

The examination included the evaluation of one applicant for senior operator license. The written examination was developed using NUREG-1021, "Operator Licensing Examination Standards for Power Reactors," Revision 9. The license examiner determined that the applicant satisfied the requirements of 10 CFR Part 55, and the appropriate license has been issued.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <u>http://www.nrc.gov/reading-rm/adams.html</u> (the Public Electronic Reading Room).

Sincerely,

/RA/

Anthony T. Gody, Chief Operations Branch Division of Reactor Safety

Dockets: 50-313 Licenses: DPR-51 Enclosure: Examination Report 05000313/2006-301 w/Attachment Supplemental Information

cc w/enclosure: Senior Vice President & Chief Operating Officer Entergy Operations, Inc. P.O. Box 31995 Jackson, MS 39286-1995

Vice President Operations Support Entergy Operations, Inc. P.O. Box 31995 Jackson, MS 39286-1995

Manager, Washington Nuclear Operations ABB Combustion Engineering Nuclear Power 12300 Twinbrook Parkway, Suite 330 Rockville, MD 20852

County Judge of Pope County Pope County Courthouse 100 West Main Street Russellville, AR 72801

Winston & Strawn LLP 1700 K Street, N.W. Washington, DC 20006-3817

Bernard Bevill Radiation Control Team Leader Division of Radiation Control and Emergency Management Arkansas Department of Health 4815 West Markham Street, Mail Slot 30 Little Rock, AR 72205-3867

James Mallay Director, Regulatory Affairs Framatome ANP 3815 Old Forest Road Lynchburg, VA 24501 Entergy Operations, Inc.

Electronic distribution by RIV: Regional Administrator (**BSM1**) DRP Director (**ATH**) DRS Director (**DDC**) DRS Deputy Director (**RJC1**) Senior Resident Inspector (**RWD**) Branch Chief, DRP/E (**DNG**) Senior Project Engineer, DRP/E (**VGG**) Team Leader, DRP/TSS (**RLN1**) RITS Coordinator (**KEG**) DRS STA (**DAP**) J. Dixon-Herrity, OEDO RIV Coordinator (**JLD**) **ROPreports** ANO Site Secretary (**VLH**)

 SUNSI Review Completed:
 Y\_ADAMS:
 Yes
 □ No
 Initials:
 \_ATG\_\_\_\_\_

 ■Publicly Available
 □ Non-Publicly Available
 □ Sensitive
 Non-Sensitive

SOE:OB	C:OB	C:PBE	C:OB		
GWJohnston/Imb	ATGody	DNGraves	ATGody		
/RA/	/RA/	/RA/	/RA/		
2/7/2006	2/14/06	2/14/06	2/15/06		
OFFICIAL RECORD COPY		T=T	elephone E	=E-mail	F=Fax

### ENCLOSURE

# U.S. NUCLEAR REGULATORY COMMISSION REGION IV

Docket:	50-313
License:	DPR-51
Report No.:	05000313/2006-301
Licensee:	Entergy Operations, Inc.
Facility:	Arkansas Nuclear One, Units 1 and 2
Location:	Junction of Hwy. 64W and Hwy. 333 South Russellville, Arkansas
Dates:	January 12, 2006
Inspector:	Gary W. Johnston, Senior Operations Engineer, Operations Branch
Approved By:	Anthony T. Gody, Chief Operations Branch Division of Reactor Safety

### SUMMARY OF FINDINGS

IR 05000313/2006-301; January 12, 2006; Arkansas Nuclear One, Unit 1; Retake Examination.

The NRC examiner evaluated the competency of one applicant for senior operator license at Arkansas Nuclear One, Unit 1. The licensee developed the examination using NUREG-1021, "Operator Licensing Examination Standards for Power Reactors," Revision 9. The written examination was administered by the facility to the applicant on January 12, 2006. The examiner determined that the applicant satisfied the requirements of 10 CFR Part 55, and the appropriate license has been issued.

### A. <u>NRC-Identified and Self-Revealing Findings</u>

None.

B. Licensee-Identified Violations

None.

#### REPORT DETAILS

#### 4. OTHER ACTIVITIES (OA)

#### 4OA5 Other Activities (Initial Operator License Examination)

#### .1 Operator Knowledge and Performance

#### a. Examination Scope

This examination was a retake of the written examination from the September 12, 2005, examination where the applicant passed the original operating examination and, therefore, no portions of an operating examination were administered during this retake examination.

On January 12, 2006, the licensee administered the examination to the applicant. The licensee staff graded the examination, analyzed the results, and presented their analysis to the NRC on January 16, 2006.

b. Findings

No findings of significance were identified.

#### .2 Initial Licensing Examination Development

a. Examination Scope

The licensee developed the examination in accordance with NUREG-1021, Revision 9. All licensee facility training and operations staff involved in examination preparation and validation were on a security agreement. The facility licensee submitted the written examination outline on October 15, 2005. The chief examiner reviewed the outline against the requirements of NUREG-1021, Revision 9, and provided comments to the licensee. The facility licensee submitted the draft examination on November 15, 2005. The chief examiner reviewed the draft examination on November 15, 2005. The chief examiner reviewed the draft examination on the examination on November 28, 2005. The licensee satisfactorily completed comment resolution on November 28, 2005.

b. Findings

The NRC approved the initial examination outline and advised the licensee to proceed with examination development.

The examiner determined that the examination initially submitted by the licensee was within the range of acceptability expected for a proposed examination.

No findings of significance were identified.

#### 3. Examination Security

#### a. Examination Scope

The examiners reviewed examination security for examination development and administration with respect to NUREG-1021 requirements.

b. Findings

No findings of significance were identified.

#### 4OA6 Meetings, Including Exit

The chief examiner presented the examination results to Mr. Randall Martin on January 12, 2006. The licensee acknowledged the findings presented.

The licensee did not identify any information or materials used during the examination as proprietary.

ATTACHMENT: SUPPLEMENTAL INFORMATION

## SUPPLEMENTAL INFORMATION

## **KEY POINTS OF CONTACT**

Licensee Personnel:

Randall Martin, Supervisor, Unit 1, Operations Training