

U.S. NUCLEAR REGULATORY COMMISSION		Conversation Date: 7/14/2005	
TELEPHONE CONVERSATION RECORD		Time: 0915	
Mail Control No.:	License No.:	Docket No.:	
Inspection # 2005-007	General	999-90001	
Licensee/Applicant Participant(s):	Organization:	Telephone No.:	
Chet Duffy, President	Ceda Mills	(724) 822-1224	
Person(s) Calling: Ronald G. Rolph			
Subject: Confirmation Needed			
<p>Summary:</p> <p>During an inspection of the licensee's facility, the licensee identified two "C" channels, used to house licensed material, staged on a pallet. The "C" channels had no labels to indicate the presence of radioactive material and the licensee did not know if the devices contained licensed material. Mr. Randy Stevens, (203) 265-5684, of Integrated Industrial Systems was contacted on June 28, 2005. Mr. Stevens confirmed that they had installed two devices on the process machine but did not leave any devices on a pallet. Mr. Stevens emphasized that they would never leave devices that were not mounted in place on a machine and had no idea if the "C" channels on the pallets contained licensed material. The licensee needs to determine if the "C" channels contain licensed material and have the devices secured by a properly licensed individual if they do contain licensed material.</p> <p>Mr. Chet Duffy agreed to determine if the "C" channels contain licensed material and get back to me by close of business on Friday July 8, 2005.</p> <p>On July 14th at 0915 Mr. Duffy left me a voice mail message. He stated that he could not find any name plate data or records in the office that indicated sources were in the devices. Mr. Duffy further stated that he spoke with Randy Stevens, Integrated Industrial Systems, Inc. (I²), and requested that I² send stickers for the devices. Mr. Duffy stated that Randy Stevens was reluctant to send labels without knowing what sources were in the devices. Per the voice mail, Mr. Duffy has requested I² to send field agent Tim Connley to determine if sources are present in the devices.</p> <p>At 1115, contact was made with Mr. Duffy. He stated that he could not determine if sources are in the devices. Mr. Duffy also stated that he believes the sources were removed when I² installed the new sources in the present devices.</p> <p>On July 20th at approximately 1000, Mr. Randy Stevens, of I², was contacted to discuss the CEDA Mills "C" channels and determine the anticipated schedule when the "C" channels would be investigated. Mr. Stevens stated that he had discussed the issue with his service technician, Mr. Tim Connely, and Tim thought they were Gamma Instruments devices. Mr. Stevens questioned whether he could investigate</p>			

the devices if they were Gamma Instruments, because they are not listed on his license, 06-21253-01.

On July 20th at approximately 1400, Mr. Randy Stevens, of I², was contacted to discuss their license and the issue of investigating the Gamma Instruments devices under their current license. Mr. Stevens was informed that if they desired to work on the "C" channels and they were in fact Gamma Instruments devices, I² would have to submit an amendment request for their license to include the Gamma Instruments devices. Mr. Stevens requested that the wording needed for the amendment be emailed to him. The appropriate wording was emailed to MR. Stevens (See attached).

Action Required/Taken:

Prepared By: Ronald G. Rolph

Date: 7/25/2005

Document Availability:

Publicly Available

Non-Publicly Available

Non-Sensitive

Non-Sensitive Copyright

Sensitive

Sensitive Copyright

Immediate Release

Normal Release Date

Delay Release Date

Prepared & SISP Review Completed By:

/ RA /

RRolph

3/7/2006

(Name)

(Date)