

U.S. NUCLEAR REGULATORY COMMISSION	Date: 03/13/06
TELEPHONE CONVERSATION RECORD	Time: 0900
Mail Control 2006001 or Report No(s).	License No(s). 29-30922-01 Docket No(s). 03036601
Name of Licensee:	East Brunswick Surgery Center, LLC d/b/a Robert Wood Johnson Surgery Center
Name of Participant(s):	Christine Reilly, Administrator
Telephone No.	732-390-4300
Subject: <small>(NOTE: This will be used as the Documents Title in ADAMS)</small>	Phone Inspection Performed 3/13/06
Summary:	<p>Spoke with Ms. Reilly regarding the license for 35.400 activities that was issued to East Brunswick Surgery Center, LLC (EBSC) on July 20, 2004. Ms. Reilly stated that no procedures have been performed using licensed material and that none were currently scheduled. The surgery center has only performed one brachytherapy procedure since opening. The nuclide used for the procedure was Pd-103.</p> <p>I informed Ms. Reilly that EBSC must contact the NRC once licensed activities begin. Ms. Reilly stated that she would contact the NRC prior to performing licensed activities.</p> <p>This telephone record will serve as documentation of the phone inspection that was performed.</p>
Action Required:	Update next required inspection date to 3/2007.
Document Availability:	<input checked="" type="checkbox"/> Publicly Available <input type="checkbox"/> Non-Publicly Available <input checked="" type="checkbox"/> Non-Sensitive <input type="checkbox"/> Non-Sensitive Copyright <input type="checkbox"/> Sensitive <input type="checkbox"/> Sensitive Copyright <input type="checkbox"/> Immediate Release <input checked="" type="checkbox"/> Normal Release <input type="checkbox"/> Delay Release Date
Prepared & SISP Review Completed By:	/ RA / CHott Date: 3/13/06