

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Vicky Savas, M.D. P.C.
27211 Lahser Road
Suite 202
Southfield, MI 48034

2. NRC REGIONAL OFFICE:

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
2443 WARRENVILLE ROAD, SUITE 210
Lisle, IL 60532-4352

REPORT 2006-001

3. DOCKET NUMBER(S)

030-36886

4. LICENSEE NUMBER(S)

21-32561-01

5. DATE(S) OF INSPECTION

March 8, 2006

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☒ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.


_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- ☐ 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Robert P. Hays		3/8/06

**Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION**

1. LICENSEE Vicky Savas, M.D., P.C. REPORT NUMBER(S) 2006-001		2. NRC/REGIONAL OFFICE Region III	
3. DOCKET NUMBER(S) 03036886	4. LICENSE NUMBER(S) 21-32561-01	5. DATE(S) OF INSPECTION March 8, 2006	
6. INSPECTION PROCEDURES USED 87130	7. INSPECTION FOCUS AREAS 03.01 - 03.07		
SUPPLEMENTAL INSPECTION INFORMATION			
1. PROGRAM CODE(S) 02201	2. PRIORITY 5	3. LICENSEE CONTACT Laura Smith, RSO	4. TELEPHONE NUMBER 248/356-5033

<input checked="checked" type="checkbox"/> Main Office Inspection	Next Inspection Date: March 2011
<input type="checkbox"/> Field Office	
<input type="checkbox"/> Temporary Job Site	

PROGRAM SCOPE

The licensee was a medical clinic located in Southfield, MI, and authorized by the license to use any byproduct material for any imaging and localization study as needed permitted by 10 CFR 35.200. Licensed activities were conducted in the nuclear medicine/cardiac stress test/scanning rooms at the authorized location as indicated on the license. The nuclear medicine department was staffed with one nuclear medicine technologist (NMT). The NMT routinely conducted six cardiac studies using Cardiolite®, Monday through Thursday, each week. The licensee received unit doses as ordered from a local nuclear pharmacy. All waste was held for decay-in-storage (DIS) or returned to the nuclear pharmacy as a limited quantity shipment. Licensed activities began during July 2005.

Performance Observations

During the inspection, the licensee's RSO demonstrated/discussed: (1) area surveys and survey meter use; (2) package check-in procedures and wipe test counting; (3) dosimetry; (4) dose calibrator checks; (5) security; and (6) consultant audits.