

Braidwood Groundwater Contamination (Update) – As of December 4, 2005, the licensee has reported measurable levels of tritium in offsite groundwater wells that were installed last week. Nearby residential wells have not shown any tritium above normal background. However, the licensee detected elevated levels of tritium (as high as approximately 33,700 picoCuries per liter) in monitoring wells in a vacant development immediately offsite. The licensee continues to monitor and to develop plans for remediation.

D-112