NRC FORM 591M PAR (10-2003) 10 CFR 2.201		ON REPORT AN	U.S. NUCLEA ID COMPLIANCE INSPECTIO	R REGULATORY COMMISSION	
LICENSEE/LOCATION INSPECTED: Medicor Cardiology, PA 225 Jackson Street Bridgewater, NJ 08807 REPORT Nos 2006001			2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415		
3. DOCKET NUMBER(S		ENSE NUMBER(S)	5. DATE(S)	OF INSPECTION	
030-33535	·	30149-01		20, 2006	
Nuclear Regulatory Comrof procedures and repres X 1. Based on the X 2. Previous vio 3. The violation identified, non-r NUREG-1600,	nission (NRC) rules and regulation entative records, interviews with per entative records, interviews with per entative records, interviews with per entative records, no violations lation(s) closed. In (s), specifically described to you be epetitive, and corrective action was to exercise discretion, were satisficative.	ns and the conditions ersonnel, and observations were identified. by the inspector as not so is being taken, ared.	as they relate to radiation safety and to of your license. The inspection consiste tions by the inspector. The inspection functived violations, are not being cited been dispersionally the remaining criteria in the NRC Enforcement (s) and Corrective Action	ed of selective examinations indings are as follows: cause they were self- brocement Policy,	
			and/or attached, were in violation of NRC pject to posting in accordance with 10 C		
corrective actions is made	30 days, the actions described by e in accordance with the requirement	me to the inspector wents of 10 CFR 2.201 at no further written re	ve Actions for Item 4, above. ill be taken to correct the violations iden (corrective steps already taken, corrective sponse to NRC will be required, unless Signature	tified. This statement of we steps which will be taken,	
LICENSEE'S REPRESENTATIVE NRC INSPECTOR	Todd J. Jackson, CHP		/RA/	03/20/2006	