NRC FORM 591M PAR (10-2003) 10 CFR 2.201		PECTION REPORT AI		S. NUCLEAR REGULATO  SPECTION	RY COMMISSION
LICENSEE/LOCATION INSPECTED:     Commonwealth Environmental Associates, Inc.     7411 Iron Bridge Road     Richmond, Virginia 23237  REPORT Nos 2006-001			2. NRC/REGIONAL OFFICE  U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415		
3. DOCKET NUMBER(		4. LICENSE NUMBER(S)	15	. DATE(S) OF INSPECTION	
030-33525	<i>&gt;</i> )	45-25295-01		April 6, 200	
LICENSEE:				,	
Nuclear Regulatory Coming of procedures and repressor X 1. Based on the 2. Previous vio	mission (NRC) rules and uentative records, interview e inspection findings, no validition(s) closed.		of your license. The inspect ations by the inspector. The	ion consisted of selective e inspection findings are as f	xaminations ollows:
identified, non-ı		I to you by the inspector as no action was or is being taken, a re satisfied.			
Non-C	ited Violation(s) was/were	discussed involving the follow	ving requirement(s) and Corre	ective Action(s):	
	s form is a NOTICE OF \	activities, as described below /IOLATION, which may be su	bject to posting in accordanc	e with 10 CFR 19.11.	and are
		Statement of Correct			
corrective actions is made	e in accordance with the rewill be achieved). I unde	cribed by me to the inspector or equirements of 10 CFR 2.201 rstand that no further written or ted Name	(corrective steps already tak esponse to NRC will be requ	en, corrective steps which	will be taken,
LICENSEE'S REPRESENTATIVE					
NRC INSPECTOR	Ronald G. Rolph		/ <b>R</b>	PA/	04/06/06