# PETERS ENGINEERS

100 ROBBINS AVENUE BERWICK, PA 18603 TEL 570 752-8044 FAX 570 752-4434 CALL TOLL FREE 1-877-752-4123

April 25, 2006

VIA FACSIMILE 1-610-337-5269

BC3

United States Nuclear Regulatory Commission Region I 475 Allendale Road King of Prussia, PA 19406-1415

RE: Request to Remove Current Storage Address and Add New Storage Address for License No.#37-31135-01

03037151

Attention LAT:

I am writing to request that the storage address named on our current license be removed and a new storage address be added for the Troxler 3411-8" Nuclear Moisture/Density Gauge that was just purchased by my Company.

The new storage address is:

Criterium-Peters Engineers 1023 Mullberry Street Berwick, PA 18603

The gauge was delivered to my office on Friday, April 21, 2006 and has not been used. I have enclosed a copy of the results of the last leak test that was performed on April 4, 2006.

Thank you for your consideration of this request and your attention to this matter.

Singerely, Dernia R. Peters

Dennis R. Peters

President

DRP/kjs

encl.

LICENSED PROFESSIONAL ENGINEERS

BUILDING DIAGNOSTICS
RESIDENTIAL INSPECTIONS
COMMERCIAL INSPECTIONS
ENVIRONMENTAL ASSESSMENTS
STRUCTURAL DESIGN

\39.760 nmss/rgni materials-c02



# Troxler Electronic Laboratories, Inc.

3008 Cornwallis Rd., P.O. Box 12057 Research Triangle Park, NC 27709 Tel: (877) 876-9537 Fax: (919) 485-2250

License: NC 032-0182-1

## **LEAK TEST CERTIFICATE**

D	E	VI	C	E:
---	---	----	---	----

Model: 3411

Serial No: 11274

### **SEALED SOURCES:**

			ACTIVITY		
SERIAL NO.	MEASURE DATE	NUCLIDE	(GBq)	(mCi)	
47-6615	5/24/1984	AM-241:BE	1.48	40	
40-8785	7/30/1984	CS-137	0.296	8	

### **LEAK TEST ANALYSIS:**

Sample collected on: 04/04/2006

Sample analyzed on:

04/04/2006

at 8:54:00 AM

Analyzed by:

HARRY P. PENDLETON, JR.

	ALPHA	BETA-GAMMA
Conversion factor (cpm/Bq)	1.28E+01	2.04E+01
Background measurement (cpm)	1	28
Sample measurement (cpm)	1	25
Activity (Bq)	< MDA	< MDA
Min. Detectable Activity (8q)	6.1E-01	1.3E+00

This certifies that the above leak test results are:  Less than 185 Bq (0.005 uCi)	Greater than 185 Bq (0.005 uCi)
If greater than 185 Bq (0.005 uCi):	
Person Notified	Date
Phone and/or	Fax

This is to acknowledge to	he receipt of your letter/application dated
	and to inform you that the initial processing which we review has been performed.
There were no admin	+ 37 - 31135-01 istrative omissions. Your application was assigned to a
technical reviewer. P	lease note that the technical review may identify additional additional information.
Please provide to this	office within 30 days of your receipt of this card
	s been forwarded to our License Fee & Accounts Receivable you separately if there is a fee issue involved.
When calling to inquire a	signed Mail Control Number 139760.  about this action, please refer to this control number.  337-5398, or 337-5260.
NRC FORM 532 (RI)	Sincerely,
(6-96)	Licensing Assistance Team Leader