

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:
Centocor Biologics, Inc.
St. Louis, Missouri2. NRC/REGIONAL OFFICE
U.S. Nuclear Regulatory Commission
Region III
2443 Warrenville Road
Lisle, Illinois 60532-4352

REPORT 2006-001

3. DOCKET NUMBER(S)

030-36018

4. LICENSEE NUMBER(S)

24-32396-01

5. DATE(S) OF INSPECTION

3/28/06

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☒ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):


- ☐ 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Michael M LaFranco	Michael M LaFranco	3/28/06

Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION

1. LICENSEE Centocor Biologics, LLC REPORT NUMBER(S) 2006-001		2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road Lisle, IL 60532	
3. DOCKET NUMBER(S) 030-36018	4. LICENSE NUMBER(S) 24-32396-01	5. DATE(S) OF INSPECTION 3/28/2006	
6. INSPECTION PROCEDURES USED 87124	7. INSPECTION FOCUS AREAS 03.01-03.07		
SUPPLEMENTAL INSPECTION INFORMATION			
1. PROGRAM CODE(S) 03620	2. PRIORITY K5	3. LICENSEE CONTACT Brenda Murray - RSO	4. TELEPHONE NUMBER 314-733-3034
<input checked="" type="checkbox"/> Main Office Inspection Next Inspection Date: NA - License Terminated			
<input type="checkbox"/> Field _____			
<input type="checkbox"/> Temporary Job Site _____			

PROGRAM SCOPE

The licensee is authorized to perform research and development activities at the facility located in St. Louis, Missouri. The licensee has not used licensed material since the license was issued. The licensee submitted a termination request earlier this year.

Observations

The inspector performed a review of licensee documentation, interviews with licensee personnel and performed independent radiation surveys to confirm that no licensed material had been possessed or used since the license was issued. The license has since been terminated by NRC.