

**U.S. NUCLEAR REGULATORY COMMISSION**

Date: 5/24/2006

**TELEPHONE CONVERSATION RECORD**

Time: 8:30 AM

Mail Control 2006-001 License No(s). 45-25374-01 Docket No(s). 030-34284  
or Report No(s).

Name of Licensee: Foundation Engineering Science, Inc. (FES)

Name of Participant(s): Raja El-Awar, P.E. - RSO and Principal for FES  
Kathy Dolce Modes - Health Physicist for NRC

Telephone No. 757-873-4113

Subject: inspection findings

(NOTE: This will be used as the Documents Title in ADAMS)

Summary: I informed the licensee's principal/RSO that I inspected their Fredericksburg facility on May 15, 2006 and that there were some findings.

1. I reviewed the 10 CFR 30.34(i) security issue and described what I had seen. The RSO indicated that he will have this corrected.
2. I asked if he had done any annual reviews of the Fredericksburg facility and the RSO stated that the gauge has only been there a year and even though he has gone over there - he had not done any annual review. The RSO said that if his personnel there cannot perform their radiation safety duties, he will move the gauges to his Newport News facility and remove Fredericksburg from the license.
3. I asked if leak tests were performed. The RSO stated that he brought the kits and showed his personnel how to do it, but they were not done. He will double check and get back to me.

The licensee's RSO committed to visiting the Fredericksburg facility on Friday and correcting the above mentioned deficiencies. The licensee will send me an email with his results.

Action Required: Wait for additional info from licensee.

Document Availability:  Publicly Available  Non-Publicly Available

Non-Sensitive  Non-Sensitive Copyright  Sensitive  Sensitive Copyright

Immediate Release  Normal Release  Delay Release Date

Prepared &amp; SUNSI Review Completed By: Kathy Dolce Modes / RA / Date: 5/24/2006