

23

From: Charles Phillips
To: Mark ring; Paul Pelke; Riemer, Kenneth
Date: Thu, Oct 21, 2004 9:26 AM
Subject: Senator Durbin Response

The other known leaks at Dresden were in 1994.

A leak was discovered on a 4" condensate storage tank supply line on Sept. 15, 1994 and a leak was discovered on the 18" HPCI return line on September 29, 1994. Both of these leaks were repaired by pipe patches.

C-29