Third Planning Meeting for the International Cooperative Group and Research Program for Proactive Materials Degradation Management - M_{ay} 11 - 13, 2006 Mills House Hotel, Charleston, South Carolina, USA

Agenda

Thursday, May 11, 2006			
9:00 am - 10:15 am	Welcome , Overview of PMDM International Cooperation , and Q&A	Joe Muscara, USNRC	
10:15 am - 10:30 am	Break		
10:30 am - 12:00 am	Short 10 minute Presentations by Participants		
12:00 am - 1:00	Lunch		
<u>1</u> , ava	Three Break Out Groups: Material Degradation and Mechanisms		
1:00 pm - 5:00 pm	Mechanisms Miligation and Repair NDE and Monitoring Write Brief Research overview Papers	All Attendees	

Friday, May 12, 2006				
	Break Out Groups Continue to			
8:30 am - Noon	Develop Research overview Papers	All Attendees		
N (00	TT T			
Noon - 1:00 pm	Lunch			
	Break Out Groups Continue to			
1:00 pm - 5:00 pm	Develop overview Papers	All Attendees		

Saturday, May 13, 2006				
	Summary Presentation of Break Out			
	Group on Materials and Degradation			
8:30 am – 9:15 am	Mechanisms	Co-Chairs		
	Summary Presentation of Break Out			
9:15 am – 9:45 am	Group on Mitigation and Repair	Co-Chairs		
	Summary Presentation of Break Out	Co-Chairs		
9:45 am - 10:15 am	Group on NDE and Monitoring			
10:15 am - 10:30				
am	Break			
	Discussion of Break Out Group			
	Reports, Summary of Meeting and			
10:30am – Noon	Future Actions	Joe Muscara, USNRC		