

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED:

Sunoco, Inc. (R&M)  
Eagle Point Facility, P.O. Box 1000  
Westville, New Jersey 08093

2. NRC/REGIONAL OFFICE

U.S. Nuclear Regulatory Commission  
Region I, 475 Allendale Road  
King of Prussia, Pennsylvania 19406-1415

REPORT Nos 2006-001

3. DOCKET NUMBER(S)

030-36899

4. LICENSE NUMBER(S)

29-31029-01

5. DATE(S) OF INSPECTION

May 26, 2006

**LICENSEE:**

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.



Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

License Condition NO 25 requires that the licensee conduct its program in accordance with procedures, statements and representations contained in application dated March 24, 2005. Application dated March 24, 2005 requires that the licensee ~~perform~~ either perform an evaluation demonstrating that unmonitored individuals are not likely to receive a radiation dose in one year in excess of 10% of the allowable limits in 10 CFR part 20 or provide dosimetry. Contrary to the above, as of May 26, 2006 the licensee did not conduct/perform the required evaluation or provide dosimetry. The licensee stated that they will perform the required evaluation and keep it on file.

**Licensee's Statement of Corrective Actions for Item 4, above.**

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	PAUL JOHNSTON		5/26/06
NRC INSPECTOR	Judith A. Joustra		5/26/06