NRC FORM 591M PAR (10-2003)	Т1			U.S. NUCLEAR REGULATO	RY COMMISSION
10 CFR 2.201	SAFETY INSI	PECTION REPORT A	ND COMPLIANCE IN	NSPECTION	
LICENSEE/LOCATION INSPECTED:     Erdman Anthony Associates     3 Crossgate Drive, Suite 100     Mechanicsburg, Pennsylvania 17055-2459  REPORT Nos 2006001			2. NRC/REGIONAL OFFICE  U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415		
3. DOCKET NUMBER(		4. LICENSE NUMBER(S)		5. DATE(S) OF INSPECTI	ON
03019413	- /	37-20558-01		May 11, 20	
LICENSEE:					
The inspection was an ex Nuclear Regulatory Coming of procedures and repression in the second	mission (NRC) rules and rentative records, interview e inspection findings, no valation(s) closed.  n(s), specifically described repetitive, and corrective at to exercise discretion, we itted Violation(s) was/were	regulations and the condition is with personnel, and observiolations were identified.  If to you by the inspector as notion was or is being taken, are satisfied.  It is a satisfied.	s of your license. The inspector. The vations by the inspector. The vations by the inspector. The value on-cited violations, are not be and the remaining criteria in a swing requirement(s) and Co	olation of NRC requirements a	examinations follows:
corrective actions is made	30 days, the actions desc e in accordance with the r e will be achieved). I unde	equirements of 10 CFR 2.20	will be taken to correct the value of the va	<b>1 4, above.</b> violations identified. This state taken, corrective steps which quired, unless specifically requature	will be taken,
NRC INSPECTOR	Jame	es Schmidt		/RA/	5/11/06