NRC FORM 591M PART 1	1			U.S. NUCLEAR REGULAT	ORY COMMISSION
(10-2003) 10 CFR 2.201					
	AFETY INSPEC	CTION REPORT	AND COMPLIANC	E INSPECTION	
1. LICENSEE/LOCATION INSPECTED:			2. NRC/REGIONAL OFFICE		
COMO Tech Inspection, Inc 27640 West 83" Street			LISNEC Pagion IV		
Lenexa, Kansas 66227			USNRC Region IV 611 Ryan Plaza Drive Arlington, Texas  76011-4005		
,			Arlington, Texas	76011-4005	
REPORT NUMBER(S) 06	6-001				
3. DOCKET NUMBER(S)		4. LICENSEE NUMBER(S)		5. DATE(S) OF INSPECTION	1
030-30996		15-26978-01		May 31, 2006	
LICENSEE:				<b>j</b> ,	
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:     X  1. Based on the inspection findings, no violations were identified.    Q  2. Previous violation(s) closed.    3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.					
cited. This form is			v and/or attached, were in vic t to posting in accordance wi		and are being
corrective actions is made in	) days, the actions desc a accordance with the re	ribed by me to the inspector equirements of 10 CFR 2.20	ctive Actions for Item 4 will be taken to correct the vi 1 (corrective steps already ta	olations identified. This state ken, corrective steps which v	vill be taken,
Title	,	ed Name	response to NRC will be req	gnature	Date
LICENSEE'S REPRESENTATIVE				g	
NRC INSPECTOR		e Donovan	/	'RA/	5/31/2006
NING FOR WEST WE PART F (10	-2003)				