NRC FORM 591M PAR (10-2003) 10 CFR 2.201	Т 1		ı	U.S. NUCLEAR REGULATO	ORY COMMISSION
10 CFR 2.201	SAFETY INSP	PECTION REPORT A	ND COMPLIANCE II	NSPECTION	
1. LICENSEE/LOCATION INSPECTED: Agilent Technologies, Inc. 2850 Centerville Road Wilmington, Delaware 19808  REPORT Nos 2006-001			2. NRC/REGIONAL OFFICE  U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415		
REPORT Nos 2006- 3. DOCKET NUMBER(S		4. LICENSE NUMBER(S)		5. DATE(S) OF INSPECTI	ON
03032792	))	07-28762-01		6/1/06 and 6/7/06	ON
LICENSEE:		0. 20.02 0.		or troo and or troo	
Nuclear Regulatory Comrof procedures and representations of the second s	nission (NRC) rules and rentative records, interview is inspection findings, no validation(s) closed.  (s), specifically described epetitive, and corrective a to exercise discretion, we steed Violation(s) was/were steed Violation(s) was/were as form is a NOTICE OF V	regulations and the condition is with personnel, and observiolations were identified.  It to you by the inspector as notion was or is being taken, are satisfied.  It discussed involving the followance in the fo	s of your license. The inspervations by the inspector. The on-cited violations, are not the and the remaining criteria in wing requirement(s) and Control of the control of	olation of NRC requirements ance with 10 CFR 19.11.	examinations follows:
corrective actions is made	30 days, the actions desc e in accordance with the re will be achieved). I under	equirements of 10 CFR 2.20	will be taken to correct the 1 (corrective steps already to response to NRC will be re	1 4, above. violations identified. This stat taken, corrective steps which quired, unless specifically rec gnature	will be taken,
LICENSEE'S REPRESENTATIVE					
NRC INSPECTOR	Stephen Hamman	ın			