



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-4005

June 8, 2006

Tim Bickett
Radiation Safety Officer
Goodwell, Inc.
P.O. Box 195
Upton, Wyoming 82730

SUBJECT: NRC INSPECTION REPORT 030-06812/2006-001 AND NOTICE OF VIOLATION

Dear Mr. Bickett:

This refers to the inspection conducted on May 15, 2006, at Goodwell, Inc. in Upton, Wyoming. The preliminary inspection results were discussed with you at the conclusion of the onsite inspection. The inspection results were also discussed with you during a final telephonic exit briefing conducted on May 23, 2006.

This inspection was an examination of activities conducted under your license as they relate to radiation safety and compliance with the Commission's rules and regulations and with the conditions of your license. Within these areas, the inspection consisted of selected examination of procedures and representative records, observations of activities, independent measurements, and interviews with personnel.

Based on the results of this inspection, the NRC has determined that a Severity Level IV violation of NRC requirements occurred. This violation was evaluated in accordance with the NRC Enforcement Policy. The current Enforcement Policy is included on the NRC's Web site at www.nrc.gov; select **What We Do, Enforcement**, then **Enforcement Policy**. The violation is cited in the enclosed Notice of Violation (Notice) and the circumstances surrounding it is described in detail. The violation is being cited in the Notice because it was identified by the NRC during the inspection.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. For your consideration and convenience, an excerpt from NRC Information Notice 96-28, "SUGGESTED GUIDANCE RELATING TO DEVELOPMENT AND IMPLEMENTATION OF CORRECTIVE ACTION," is enclosed. The NRC will use your response, in part, to determine whether further enforcement action is necessary to ensure compliance with regulatory requirements.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter, its enclosures, and your response will be made available electronically for public inspection in the NRC Public Document Room or from the NRC's document system (ADAMS), accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html>. To the extent possible, your response should not include any personal privacy, proprietary, or safeguards information so that it can be made available to the public without redaction.

Goodwell, Inc.

-2-

Should you have any questions concerning this inspection or the enclosed report, please contact Linda M. Gersey at (817) 860-8299 or the undersigned at (817) 860-8143.

Sincerely,

/RA/

Vivian H. Campbell, Chief
Nuclear Materials Inspection Branch

Docket No.: 030-06812
License No.: 49-12994-01

Enclosures:

1. Notice of Violation
2. NRC Information Notice 96-28

cc w/Enclosure 1:
Wyoming Radiation Control Program Director

Goodwell, Inc.

-3-

bcc w/enclosure 1 (via ADAMS distrib):

LDWert

CLCain

VHCampbell

JEWhitten

LMGersey

KEGardin

NMIB

RIV Materials Docket File (5th floor)

SUNSI Review Completed: LMG ADAMS: X Yes No Initials: LMG

X Publicly Available Non-Publicly Available Sensitive X Non-Sensitive

DOCUMENT NAME: E:\Filenet\ML061630442.wpd

final r:_dnms

RIV:DNMS:NMIB	C:NMLB	C:NMIB
LMGersey	JEWhitten	VHCampbell
<i>/RA/</i>	<i>/RA JDCook for/</i>	<i>/RA/</i>
05/25/06	06/05/06	06/08/06

OFFICIAL RECORD COPY

T=Telephone

E=E-mail

F=Fax

ENCLOSURE 1

NOTICE OF VIOLATION

Goodwell, Inc.
Upton, Wyoming

Docket No. 030-06812
License No. 49-12994-01

During an NRC inspection conducted on May 15, 2006, a violation of NRC requirements was identified. In accordance with the NRC Enforcement Policy, the violation is listed below:

10 CFR 39.13(d) requires, in part, that the applicant establish and submit to the Commission its program for annual inspections of the job performance of each logging supervisor.

License Condition 15 incorporates the inspection program containing the requirements of 10 CFR 39.13(d), as submitted in the licensee's application dated January 14, 2003.

Contrary to the above, as of May 15, 2006, job performance inspections for all logging supervisors who had worked at the Upton, Wyoming facility, had not been performed for calendar years 2004 and 2005.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, Goodwell, Inc. is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, DC 20555, with a copy to the Regional Administrator, Region IV, 611 Ryan Plaza Drive, Suite 400, Arlington, Texas 76011, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation, or, if contested, the basis for disputing the violation or severity level, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. Your response may reference or include previous docketed correspondence, if the correspondence adequately addresses the required response. If an adequate reply is not received within the time specified in this Notice, an order or a Demand for Information may be issued as to why the license should not be modified, suspended, or revoked, or why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to extending the response time.

If you contest this enforcement action, you should also provide a copy of your response, with the basis for your denial, to the Director, Office of Enforcement, United States Nuclear Regulatory Commission, Washington, DC 20555-0001.

Because your response will be made available electronically for public inspection in the NRC Public Document Room or from the NRC's document system (ADAMS), accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html>, to the extent possible, it should not include any personal privacy, proprietary, or safeguards information so that it can be made available to the public without redaction. If personal privacy or proprietary information is necessary to provide an acceptable response, then please provide a bracketed copy of your response that identifies the

information that should be protected and a redacted copy of your response that deletes such information. If you request withholding of such material, you must specifically identify the portions of your response that you seek to have withheld and provide in detail the bases for your claim of withholding (e.g., explain why the disclosure of information will create an unwarranted invasion of personal privacy or provide the information required by 10 CFR 2.390(b) to support a request for withholding confidential commercial or financial information). If safeguards information is necessary to provide an acceptable response, please provide the level of protection described in 10 CFR 73.21.

In accordance with 10 CFR 19.11, you may be required to post this Notice within two working days.

Dated this 8th day of 2006