

OCT 18 1990

*License Docket  
Folder*

Department of the Army  
Commander, Tripler Army Medical Center  
ATTN: HSHK-RP (Radiation Protection Office)  
Tripler AMC, Hawaii 96859

Attention: Captain Loyd Carroll  
Health Physics Officer

Gentlemen:

Please find enclosed NRC Form-591 which indicates 1 violation that was identified during the safety inspection which was conducted on October 1 and 2, 1990 of activities authorized by NRC License No. 53-00458-04.

Pursuant to the provisions of 10 CFR 2.202, you are requested to sign and date the enclosed NRC Form-591 which indicates that appropriate corrective action will be taken with reference to the violation(s) described on the form. After signing, please detach the first sheet of NRC Form-591 and return the remaining carbon copies with your signature to me at the Region V office, address identified above, within 30 days of the date of this letter.

If you have any questions on this matter or concerning this inspection, please telephone me on 415-943-3765.

Thank you for your cooperation.

Sincerely,

*Beth A. Riedlinger*

Beth A. Riedlinger  
Senior Health Physicist (Licensing)  
Nuclear Materials and  
Fuel Fabrication Branch

Enclosure:  
NRC Form-591

*A/2*

Distribution

bcc w/original concurrence, copy of license, and original correspondence:

License docket folder (Peggy)

bcc w/copy of license and correspondence:

Inspection folder (Peggy)

bcc w/copy of license:

Reading file (Frances)

bcc w/correspondence and 2 copies of license:

Maurice Messier, LFMB, MNBB 4503

license only:

State of California

F. Browne

/ /

J. Montgomery

/ /

D. Skov

/ /

<sup>BRK</sup>  
B. Riedlinger

10/11/8190

REQUEST COPY ]	REQUEST COPY ]	REQUEST COPY ]	REQUEST COPY ]	REQUEST COPY ]
YES / NO ]	YES / NO ]	YES / NO ]	YES / (NO) ]	YES / NO ]