

LANDMARK BUILDING, STE. 300 1062 BARNES RD., WALLINGFORD, CT 06492 TEL. 203-265-9831 FAX 203-265-2977

RICHARD A. BUGLIARI, M.D., F.A.C.C.
WILLIAM J. FARRELL, M.D., F.A.C.C.
ROBERT J. GOLUB, M.D., F.A.C.C.
MICHAEL V. McMAHON, P.A.-C
AMY JOCKLE, A.P.R.N.

June 19, 2006

Stephen Hammann
Health Physicist
Commercial and R&D Branch
Division of Nuclear Materials Safety
United States Nuclear Regulatory Commission, Region I
475 Allendale Road
King of Prussia, PA 19406-1415

M5 16

Q-9

06-30842-01

06-30842-01

07036420

MEGLON 1

Dear Mr. Hammann:

I am responding to your letter, dated May 24, 2006, requesting additional information concerning our application for amendment to license control #138724. Our NRC license number is 06-30842-01. Starting January 1, 2006, the 4 cardiologists from Internal Medicine Associates, P.C. at 97 Barnes Road, Wallingford, Connecticut left Internal Medicine Associates and joined our practice. The 2 groups have essentially merged. However, from a legal point of view, they have joined our practice. We are now changing the name of our practice to Cardiology Associates of Central Connecticut, LLC.

Prior to this merger, both groups had NRC licenses and nuclear cameras. Our NRC license is #06-30842-01. Their nuclear license is 06-30788-01. Our radiation safety officer is myself, Dr. Robert J. Golub. Their radiation safety officer is Dr. George Spivack.

In coming together, we decided that control of the nuclear licenses would remain unchanged. We are, in fact, making no changes whatsoever in control of either nuclear license. Nuclear license #06-30842-01 will remain fully under my control. Nuclear license #06-30788-01 will remain under fully under the control of Dr. George Spivack. We are not currently planning to merge control of the laboratories. This may be planned in the future and of course we would work with you in this regard. Currently, we are maintaining control of each license completely unchanged from previous.

The new name of our practice is Cardiology Associates of Central Connecticut, LLC. The radiation safety officer for license #06-30842-01 remains Dr. Robert J. Golub, and the licensee contact is Laurie Grimaldi, our nuclear technologist. No changes in personnel or duties that relate to the license program are anticipated. There are no new personnel. No changes in the organization, location, facilities, equipment, or procedures are anticipated or planned. The surveillance program will not change.

All records concerning the safe and effective functioning of our laboratory will remain with our laboratory. We will continue to maintain these carefully. We will also continue to abide by all constrains, conditions, requirements, and commitments of the Nuclear Regulatory Commission.

LANDMARK BUILDING •1062 BARNES ROAD • SUITE 300 • WALLINGFORD, CT 06492 • (203) 265-9831 FAX 265-2977



LANDMARK BUILDING, STE. 300
1062 BARNES RD., WALLINGFORD, CT 06492
TEL. 203-265-9831 FAX 203-265-2977
RICHARD A. BUGLIARI, M.D., F.A.C.C.
WILLIAM J. FARRELL, M.D., F.A.C.C.
ROBERT J. GOLUB, M.D., F.A.C.C.
MICHAEL V. McMAHON, P.A.-C

AMY JOCKLE, A.P.R.N.

Page 2

Bottom line, we have joined together with another cardiology practice in our community. We are now a 7-physician practice. We are not, however, changing or altering control over NRC licenses. The control of NRC license #06-30842-01 will remain unchanged as will control over license 06-30788-01. We will maintain separate radiation safety officers for now for each license. We anticipate no significant changes in any of the operational aspects of our program.

I hope that this information clarifies the letter you sent dated May 24, 2006. Please let me know if I can help in any way or supply more information.

(b)

Sincerely,

Robert J. Golub, M.D., F.A.C.C.

RJG/gsa

D: 06/19/2006 T: 06/19/2006