

## UNITED STATES NUCLEAR REGULATORY COMMISSION

## REGION IV 611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-4005

June 28, 2006

Mr. Drew H. McCorkle Radiation Safety Officer Century Inspection, Inc. P.O. Box 59126 10931 Indian Trail Dallas, Texas 75229

SUBJECT: NRC INSPECTION REPORT 030-06415/2006-001 (FORM 591M Part 1)

Dear Mr. McCorkle:

This letter and the enclosed NRC Form 591M refer to the inspection conducted on June 22, 2006, at your facility located in Dallas, Texas. The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, independent measurements, and observation of activities in progress. The inspection results were discussed with you at the conclusion of the inspection.

Within the scope of this inspection no violations or deviations were identified; therefore, no response to this letter or the enclosed NRC Form 591M is required.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be available electronically for public inspection in the NRC Public Document Room or from the NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <a href="http://www.nrc.gov/reading-rm/adams.html">http://www.nrc.gov/reading-rm/adams.html</a>.

Should you have any questions concerning this inspection or the enclosed report, please contact the undersigned at (817) 276-6529.

Sincerely,

/RA/

Randy R. Erickson Nuclear Materials Inspection Branch

Docket No.: 030-06415 License No.: 42-08456-02

Enclosure: As stated

cc w/enclosure:

Texas Radiation Control Program Director

Century	Inspection,	Inc.
---------	-------------	------

-2-

bcc w/enclosure (via ADAMS e-mail distribution):

**LDWert** 

CLCain

VHCampbell

**JEWhitten** 

**JFKatanic** 

KEGardin

**NMIB** 

RIV Materials Docket Files - 5th Floor

SUNSI Review Completed: RRE

ADAMS: Yes 9No Initials: RRE

Publicly Available 9Non-Publicly Available 9Sensitive Non-Sensitive

## DOCUMENT NAME: s:\dnms\!nmib\!erickson\60641501-591M.wpd

final r:\\_dnms

RIV:DNMS:NMIB	C:NMIB
RRErickson	VHCampbell
/RA/	/RA/
06/27/06	06/28/06

NRC FORM 591M PART 1 U.S. NUCLEAR REGULATORY COMMISSION (10-2003)					RY COMMISSION	
10 CFR 2.201	SAFETY INSPI	ECTION REPORT AND	COMPLIANC	E INSPECTION		
1. LICENSEE/LOCATION INSPECTED: Century Inspection, Inc. P.O. Box 59126 10931 Indian Trail Dallas, Texas 75229-3525		1	NRC/REGIONAL OFFICE     U.S. Nuclear Regulatory Commission     Region IV     611 Ryan Plaza Drive, Suite 400     Arlington, TX 76011			
REPORT	2006-001	4 LIGENICEE NUMBER(O)		E DATE(O) OF INO	PEOTION	
3. DOCKET NUMBER(S) 030-06415		4. LICENSEE NUMBER(S) 42-08456-02		5. DATE(S) OF INSPECTION  June 22, 2006		
LICENSEE:		42-00450-02		June 22, 2000		
The inspection was an ex Nuclear Regulatory Comr of procedures and repres	nission (NRC) rules and entative records, interviev	conducted under your license as regulations and the conditions of vs with personnel, and observation	your license. The in	spection consisted of selective e	examinations	
X 1. Based on the	e inspection findings, no v	iolations were identified.				
2. Previous viol	ation(s) closed.					
	and corrective action was	to you by the inspector as non-ci or is being taken, and the remaini		,		
	Non-Cited Violation(s) w	as/were discussed involving the f	ollowing requirement	(s) and Corrective Action(s):		
cited. This form		activities, as described below and TON, which may be subject to po		•	nd are being	
	Licensee's	s Statement of Corrective	Actions for Iter	n 4, above.		
corrective actions is made	30 days, the actions desc in accordance with the re will be achieved). I under	ribed by me to the inspector will be equirements of 10 CFR 2.201 (constant that no further written respected Name	e taken to correct the	e violations identified. This state y taken, corrective steps which w	ill be taken,	
LICENSEE'S REPRESENTATIVE						
NRC INSPECTOR	Randv R. Erickso	on		/RA/	06/27/2006	