NRC FORM 591M PART 1 (10-2003)	·		U.S. NUCLEAR REGU	LATORY COMMISSION
SAFETY INS	SPECTION REPORT	AND COMPLIANO	E INSPECTION	
1. LICENSEE/LOCATION INSPECTED: MPAN TEC LLC 5063 STUMP POAD MONTGOMERYVILLE, PA. 1393		2. NRC/REGIONAL OFFICE		
REPORT NUMBER(S) 2006 -	001	,	·	
3. DOCKET NUMBER(S)	4. LICENSEE NUMBER(S)	1	5. DATE(S)	OF INSPECTION
050-36900	37-3103	0-01	JUNE	28, 2006
LICENSEE: The inspection was an examination of the ac Regulatory Commission (NRC) rules and reg	tivities conducted under your ulations and the conditions of	license as they relate to re	adiation safety and to cor	noliance with the Nuclear
procedures and representative records, inter-	views with personnel, and obs	servations by the inspector	r. The inspection finding	s are as follows:
1. Based on the inspection findings,	no violations were identified.			·
2. Previous violation(s) closed.				İ
3. The violation(s), specifically descriped non-repetitive, and corrective action exercise discretion, were satisfied.	ribed to you by the inspector a was or is being taken, and the	s non-cited violations, are r remaining criteria in the NF	not being cited because th RC Enforcement Policy, N	ey were self-identified, UREG-1600, to
·	(s) was/were discussed involvi	na the followina requiremen	nt(s) and Corrective Action	n(s):
				,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
·		•		Ī
		•		·
		. *		
4. During this inspection certain of you cited. This form is a NOTICE OF VIO				ments and are being
(Violations and Corrective Action	s)			
•				
•				
		•	•	
	•	· •		
•				
		•		
		·		
			•	
hereby state that, within 30 days, the actions or corrective actions is made in accordance with the then full compliance will be achieved). I under	he requirements of 10 CFR 2.2	or will be taken to correct to 201 (corrective steps alread sponse to NRC will be requ	he violations identified. The dy taken, corrective steps ired, unless specifically re	MINOL MILDO MINOLIT AND
	H. LADUN	P	14101	Ox -JR-M
NKU MAKEUTUR I <i>PULL II AA 1</i> 1				