

Open Generic Communication TACs (PA No. 101122CA/B)

Summary Report (04/01/2006 - 06/30/2006)

TAC NO.	TAC TITLE	STATUS	AGE	OPEN TAC	LEAD ORG
MC6900	RIS: NRC Staff Position on 10 CFR 50.36, "Tech Spec", Instrument Setting Requirements" (Gratton-DORL/Markley-DPR)	O	9 Mon	05/24/2005	DORL
MC8203	RIS: Endorsement of NEI Guidance "Enhancements to Emergency Preparedness Programs ..." (Sullivan-NSIR/Markley-DPR)	O	6 Mon	08/29/2005	NSIR
MC8897	RIS: NRC Decision to Cancel Operator Manual Action Rulemaking (Klein-DRA/Markley-DPR)	O	3 Mon	11/15/2005	DRA
MC8778	RIS: 2004-15, Supp. 1 "Emergency Preparedness Issues: Post 9/11" (Anderson-NSIR/Markley-DPR)	O	6 Mon	1/10/2006	NSIR
MC9661	RIS: Revised Review and Transmittal Process for Accident Sequence Precursor Analyses (Markley-DPR)	O	1 Mon	01/26/2006	DPR
MD1658	RIS: "Request for Licensee Information for Input into the NRC's Incident Response e-Library" (Dudek/Markley-DPR)	O	1 Mon	5/10/2006	NSIR
MD1211	RIS: "Generic Safety Issue 191 - Scheduler Considerations" (Lehning-DSS/Markley-DPR)	O	0 Mon	4/18/2006	DSS
MD2191	RIS: "Ventilation and Air Conditioning in Emergency Diesel Generator Rooms" (Hartzman/Markley-DPR)	O	0 Mon	6/7/2006	DE
MD2470	RIS: "Information on the Modification Made to the Reactor Oversight Process" (Schoenfeld/Markley-DPR)	O	0 Mon	7/3/2006	DE
MD2454	RIS: "Preparation and Scheduling of Operator Licensing Examinations" (Salgado/Markley-DPR)	O	0 Mon	6/28/2006	DE
MC9709	IN: "Service Water Silting Events" (Hanna-R4/Roquecruz-DIRS)	O	0 Mon	02/02/2006	R4
MD0030	IN: "Potential Fire Risk Involving Lithium Batteries" (Barnes-NSIR/Tabatabai-DIRS)	O	2 Mon	2/13/2006	NSIR

Open Generic Communication TACs (PA No. 101122CA/B)

Summary Report (04/01/2006 - 06/30/2006)

TAC NO.	TAC TITLE	STATUS	AGE	OPEN TAC	LEAD ORG
MD0217	IN: "River Bend Erroneous Indication of Moisture Carryover" (Clark-R4/Roquercruz-DRIS)	O	2 Mon	2/24/2006	R4
MD0347	IN: "Direct Current Distribution System Problems" (Koshy-DE/Tabatabai-DIRS)	O	1 Mon	3/14/2006	DE
MD0545	IN: "ECCS Pumps Declared Inoperable Due to Potential Post-Accident Gas Binding" (Unikewicz-DCI/Tabatabai-DIRS)	O	1 Mon	3/22/2006	DCI
MD1986	IN: "Emergency Diesel Generator Issues (Koshy-DE/Laura-DIRS)	O	1 Mon	5/24/2006	DE
MD1834	IN: "Vibration-Induced Degradation" (Unikewicz/Beaulieu-DPR)	O	1 Mon	5/22/2006	DCI
MD1918	IN: Failure of Magnesium Rotor in Motor Operated Valve Actuators" (Polickoski/Beaulieu-DPR)	O	1 Mon	5/24/2006	R2
MD1710	IN: "Recent Operating Experience on Safety/Relief Value Setpoint" (Hammer/Beaulieu-DPR)	O	1 Mon	5/15/2006	DCI
MD2101	IN: "Contamination of Onsite Ground-Water Due to Leakage from Structures, Systems, ..." (Klementowicz/Beaulieu-DPR)	O	1 Mon	5/31/2006	NMSS
MD0557	BL: "Abnormal Liquid Effluent Releases and Ground-Water Contamination Do to ..." (Klementowicz/Markley-DPR)	O	3 Mon	3/23/2006	DIRS
MC6498	GL: Post-Fire Safe-Shutdown Circuit Analysis Spurious Actuations (Wolfgang-DRA/Markley-DPR)	O	11 Mon	03/29/2005	DRA
MC6635	GL: Primary Water Stress Corrosion Cracking in Butt Welds (Sullivan-DCI/Markley-DPR)	O	10 Mon	04/06/2005	DCI
MC6893	GL: Managing Gas in Emergency Core Cooling Systems (Lyon-DSS/Markley-DPR)	O	9 Mon	05/04/2005	DSS
MC6496	GL: Failures of Inaccessible/Underground Cables That Disable Accident Mitigation Systems (Koshy-DE/Markley-DPR)	O	11 Mon	03/29/2005	DE

