



DEPARTMENT OF THE NAVY
OFFICE OF THE CHIEF OF NAVAL OPERATIONS
2000 NAVY PENTAGON
WASHINGTON, DC 20350-2000

RECEIVED
REGION 1

03029462

IN REPLY REFER TO

2006 JUN 12 PM 1: 54

5104
Ser 455C/6U838125
22 May 2006

67

From: Chairman, Naval Radiation Safety Committee
To: Commanding General, Marine Corps Logistics Command, Albany
Via: Commandant of the Marine Corps (SD)

Subj: RADIOLOGICAL AFFAIRS SUPPORT PROGRAM (RASP) RE-INSPECTION
OF MARINE CORPS LOGISTICS COMMAND, ALBANY

Ref: (a) OPNAVINST 6470.3
(b) NAVSEAINST 5100.18A
(c) NAVSEA S0420-AA-RAD-010
(d) NRSC ltr 5104 Ser N455C/N45U9011243 of 4 Mar 05
(e) NRSC ltr 5104 Ser N455C/N45U9011484 of 8 Nov 05
(f) NAVSEADET RASO ltr 67004 Ser 02A/06-0233/141 of
28 Mar 06
(g) CG MARCORLOGCOM ltr 5104 L14 of 27 Apr 06

1. References (a), (b) and (c) designate the Naval Sea Systems Command Detachment, Radiological Affairs Support Office (NAVSEADET RASO) as technical support center to the Chairman, Naval Radiation Safety Committee (CNO N45) and the Naval Sea Systems Command (SEA 04N). Under this authority, Captain Tyrone Naquin, Director, Radiological Controls, Naval Sea Systems Command (SEA 04N) and Mr. Paul Feeser of NAVSEADET RASO performed a re-inspection of radioactive commodity operations managed by the Marine Corps Logistics Command (MARCORLOGCOM), Albany from 12-14 April 2006.

2. The re-inspection evaluated radioactive commodity management operations authorized by Naval Radioactive Materials Permit (NRMP) No. 10-67004-T1NP which is issued to Marine Corps Logistics Bases, Albany (currently MARCORLOGCOM.) Previous RASP inspections of these operations conducted by NAVSEADET RASO on 24-28 January 2005 and 18-20 October 2005 resulted in the assignment of unsatisfactory ratings as reported by references (d) and (e). The re-inspections included an evaluation of the operations previously rated unsatisfactory by references (d) and (e) for compliance with references (a), (b), (c), and federal regulations, with verification of the adequacy of the corrective actions resulting from the inspections.

Subj: RADIOLOGICAL AFFAIRS SUPPORT PROGRAM (RASP) INSPECTION OF
SOUTHWEST REGIONAL MAINTENANCE CENTER

3. Overall, the performance of RASP operations at Marine Corps Logistics Command, Albany is rated as satisfactory. A satisfactory rating is given to those commands where no significant radiation safety program violations are found. A rating of unsatisfactory is given when there is an actual or substantial risk of the loss of safety or security as a result, of methods or operations.
4. Marine Corps Logistics Command, Albany has made considerable progress since the last inspection. It is apparent that management has taken an active role to correct previous program deficiencies and to ensure radioactive commodity operations are compliant with references (a), (b), (c) and federal regulations.
5. Though no findings were noted during this inspection, action items still remain open to correct findings from the inspections on 24-28 January 2005 and 18-20 October 2005. As per reference (f), progress reports on completion of corrective actions shall be provided every 60 days until all corrective actions have been completed. Your latest progress report, reference (g), is currently in review at NAVSEADET RASO. Progress reports shall continue to be submitted to Officer in Charge, NAVSEADET RASO, NWS P.O. Drawer 260, Yorktown, VA, 23691-0260, with copies to COMNAVSEASYSKOM (SEA 04N) and CNO N455.
6. For further information, contact NAVSEADET RASO at DSN 953-4692 or commercial (757) 887-4692.


L. L. FRAGOSO
By direction

Copy to:
NRC Region I
COMNAVSEASYSKOM (SEA 04N)
NAVSEADET RASO